



# ARKANSAS

ENERGY & ENVIRONMENT

10/11/2021

Mr. Robert Sanchez  
BFI Waste Systems of Arkansas  
18511 W. Sardis Road  
Bauxite, AR 72011

**RE: Inspection conducted on September 24, 2021**  
**AFIN 63-00155**  
**Permit Number 0277-S4**

Dear Mr. Sanchez,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or [davenportk@adeq.state.ar.us](mailto:davenportk@adeq.state.ar.us)

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport'.

Kim Davenport  
Solid Waste Inspector  
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



# ARKANSAS

## ENERGY & ENVIRONMENT

10/11/2021

Mr. Slade Patterson  
BFI Waste Systems of Arkansas  
7111 Old Millington Rd., Millington, TN 38053

**RE: Inspection conducted on September 24, 2021**  
**AFIN 63-00155**  
**Permit Number 0277-S4**

Dear Mr. Patterson,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or [davenportk@adeq.state.ar.us](mailto:davenportk@adeq.state.ar.us)

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport'.

Kim Davenport  
Solid Waste Inspector  
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



**ARKANSAS**  
ENERGY & ENVIRONMENT

**Office of Land Resources**  
**Regulated Waste Operations**  
**Class 4 Landfill Inspection Form**

|                          |   |                      |  |                      |          |
|--------------------------|---|----------------------|--|----------------------|----------|
| <b>Site Name</b>         | BFI Waste Systems of Arkansas, LLC- Class 4 | <b>County</b>        | Saline   | <b>AFIN</b>          | 63-00155 |
| <b>Facility Address</b>  | 18511 W. Sardis, Bauxite, AR 72011          | <b>Phone #</b>       | 901-873-8334 (Slade Patterson)<br>501-602-8440 (Robert Sanchez)  | <b>Permit Number</b> | 0277-S4  |
| <b>Permittee Address</b> | 18511 W. Sardis, Bauxite, AR 72011          | <b>Email Address</b> | <a href="mailto:SPatterson2@republicservices.com">SPatterson2@republicservices.com</a><br><a href="mailto:RSanchez2@republicservices.com">RSanchez2@republicservices.com</a> | <b>PDS#</b>          | 117765   |
| <b>Date</b>              | 9/24/2021                                   | <b>Entry Time</b>    | 0940   | <b>Exit Time</b>     | 1200     |

**Operational Standards**

**Category 1**

| <b>Regulation</b> | <b>Item Description</b>  | <b>Comments</b> |
|-------------------|--|-----------------|
| 617(a)(b)         | Record Keeping Requirements Specified by Regulations             |                 |
| 607(j)            | Adequate Provisions for Backup Equipment                         |                 |
| 619               | Annual Compliance Inspection by Registered Professional Engineer |                 |
|                   |  |                 |

**Category 2**


| <b>Regulation</b> | <b>Item Description</b>   | <b>Comments</b> |
|-------------------|---|-----------------|
| 607(a)            | Operations in Accordance with Permit Documents                  |                 |
| 613(c)            | Adequate All Weather Operational Roads                          |                 |
| 607(c)(d)         | Smallest Practical Area, Single Working Face                    |                 |
| 607(b)            | Operations by Licensed On-site Personnel at All Times           |                 |
| 607(g)            | Litter Control Provisions Maintained                            |                 |
| 622               | Survey Controls   |                 |
| 623               | Surface Water Controls  |                 |
| 607(h)(1)         | Contouring Prevents Surface Water Flowing Into or Through Waste |                 |
| 607(h)(2)         | Surface Water Control Prevents Off-site Sediment Accumulation   |                 |
| 607(i)(o)         | Adequate Maintenance of Intermediate/Final Cover Vegetation     |                 |
| 607(o)            | Leachate Leaks or Evidence of Leachate Seepage                  |                 |
|                   |   |                 |

**Category 3**

| <b>Regulation</b> | <b>Item Description</b>                                    | <b>Comments</b> |
|-------------------|--|-----------------|
| 608               | Implementation of Hazardous Waste Exclusion Plan           |                 |
| 609(a)            | Satisfactory Weekly or More Frequent Cover                 |                 |
| 609(b)            | Satisfactory Immediate Cover                               |                 |
| 615               | Cause Discharge/Leachate Discharge Leaving Landfill        |                 |
| 607(o)            | Erosion or Other Cover Defects Resulting in Exposed Refuse |                 |
| 309(c)            | Overfill/Off Lined Area                                    |                 |
|                   |  |                 |

**Records**

|                                   |           |  |     |
|-----------------------------------|-----------|--|-----|
| <b>Date of Last Annual Report</b> | 3/31/2021 | <b>Date of Last Quarterly Methane Monitoring</b> | N/A |
|-----------------------------------|-----------|--|-----|

|   |                 |  |         |             |   |             |      |
|---|-----------------|--|---------|-------------|---|-------------|------|
| <b>Date of Last Groundwater Monitoring Report</b> | N/A             | <b>Previous Quarter Waste Received</b> |         |             | N/A   |             |      |
|   |                 |  |         |             |   |             |      |
| <b>Operator Name &amp; Number</b>                 | Closed facility | <b>Signature of Inspector</b>          |         |             |  |             |      |
| <b>Exit Interview Conducted with</b>              | Robert Sanchez  | <b>Method</b>                          | On-site | <b>Date</b> | 9/24/2021   | <b>Time</b> | 1140 |