



ARKANSAS

ENERGY & ENVIRONMENT

12/28/2021

Mr. Robert Sanchez
BFI Waste Systems of Arkansas
18511 W. Sardis Road
Bauxite, AR 72011

RE: Inspection conducted on December 13, 2021
AFIN 63-00155
Permit Number 0277-S4

Dear Mr. Sanchez,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or davenportk@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport', is shown above the printed name.

Kim Davenport
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS

ENERGY & ENVIRONMENT

12/28/2021

Mr. Brad Zimmerman
BFI Waste Systems of Arkansas
5605 Moreau River Access Road
Jefferson City, MO 65101

RE: Inspection conducted on December 13, 2021
AFIN 63-00155
Permit Number 0277-S4

Dear Mr. Zimmerman,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or davenportk@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport', is shown within a rectangular box.

Kim Davenport
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

Office of Land Resources
Regulated Waste Operations
Class 4 Landfill Inspection Form

Site Name	BFI Waste Systems of Arkansas, LLC- Class 4	County	Saline	AFIN	63-00155
Facility Address	18511 W. Sardis, Bauxite, AR 72011	Phone #	901-873-8334 (Brad Zimmerman) 501-602-8440 (Robert Sanchez)	Permit #	0277-S4
Permittee Address	18511 W. Sardis, Bauxite, AR 72011	Email Address	bzimmerman2@republicservices.com RSanchez2@republicservices.com	PDS#	118595
Date	12/13/2021	Entry Time	1300	Exit Time	1515

Operational Standards

Category 1

Regulation	Item Description	Comments
617(a)(b)	Record Keeping Requirements Specified by Regulations	
607(j)	Adequate Provisions for Backup Equipment	
619	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
607(a)	Operations in Accordance with Permit Documents	
613(c)	Adequate All Weather Operational Roads	
607(c)(d)	Smallest Practical Area, Single Working Face	
607(b)	Operations by Licensed On-site Personnel at All Times	
607(g)	Litter Control Provisions Maintained	
622	Survey Controls	
623	Surface Water Controls	
607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
607(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
607(i)(o)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
607(o)	Leachate Leaks or Evidence of Leachate Seepage	

Category 3

Regulation	Item Description	Comments
608	Implementation of Hazardous Waste Exclusion Plan	
609(a)	Satisfactory Weekly or More Frequent Cover	
609(b)	Satisfactory Immediate Cover	
615	Cause Discharge/Leachate Discharge Leaving Landfill	
607(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2021	Date of Last Quarterly Methane Monitoring	N/A
-----------------------------------	-----------	--	-----

Date of Last Groundwater Monitoring Report	N/A	Previous Quarter Waste Received			0	
Operator Name & Number	Closed facility	Signature of Inspector				
Exit Interview Conducted with	Robert Sanchez	Method	On-site	Date	12/13/2021	Time 1445