



ARKANSAS

ENERGY & ENVIRONMENT

01/10/2022

Mr. Allen Thomas
Green Bay Packaging, Inc.
338 Hwy 113
Morrilton, AR 72110

RE: Inspection conducted on December 13, 2021
AFIN 15-00001
Permit Number 0284-S3N

Dear Mr. Thomas,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 410-4462 or daniel.cullum@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink that reads 'Daniel Cullum'.

Daniel Cullum
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Green Bay Packaging Inc.	County	Conway	AFIN	15-00001
Facility Address	338 Highway 113 Morrilton, AR 72110	Phone #	501-334-9289	Permit #	0284-S3N
Permittee Address	338 Highway 113 Morrilton, AR 72110	Email Address	athomas@gbp.com	PDS #	118646
Date	12/13/2021	Entry Time	1322	Exit Time	1450

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	05/28/2021	Date of Last Quarterly Methane Monitoring	NA
Date of Last Groundwater Monitoring Report	05/25/2021	Previous Quarter Waste Received	60,360.40 Cubic Yards

Operator Name & Number	Allen Thomas-004042	Signature of Inspector					
Exit Interview Conducted with	Allen Thomas	Method	On Site	Date	12/13/2021	Time	1446