



ARKANSAS

ENERGY & ENVIRONMENT

01/27/2022

Mr. Robert Hendrix
Craighead SWDA
P.O. Box 16777
Jonesboro, AR 72403

RE: Inspection conducted on January 12, 2022
AFIN 16-00923
Permit Number 0254-S1-R4

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges constitutes violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or bakert@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads "Tobin Baker".

Tobin Baker
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Craighead County SWDA Class 1	County	Craighead	AFIN	16-00199
Facility Address	238 CR 476 Jonesboro, AR 72404	Phone #	870-972-6353	Permit #	0254-S1-R4
Permittee Address	P.O. Box 16777, Jonesboro AR 72403	Email Address	rhendrix@ccswda.com	PDS #	118880
Date	1/12/2022	Entry Time	1020	Exit Time	1155

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
	411(o)	Leachate Leaks or Evidence of Leachate Seepage	
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
X	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	Leachate discharge observed on the west slope of Cell 1. (Refer to Photos #1 - #4.)
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2021	Date of Last Quarterly Methane Monitoring	11/23/2021
Date of Last Groundwater Monitoring Report	8/16/2021	Previous Quarter Waste Received	Class 1- 27,075.63 Class 4-9,123.11

Operator Name & Number	Robert Hendrix 00336	Signature of Inspector					
Exit Interview Conducted with	David Passmore	Method	On-site	Date	1/12/2022	Time	1145

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4	AFIN	16-00199
Photographer	Tobin Baker, Inspector			<i>TB</i>	Witness	N/A		
Photo #	1	Of	4		Date	1/12/2022	Time	1122
Description	Leachate discharge observed on the west slope of Cell 1.							
								
Location	Craighead County SWDA Class 1				Permit	0254-S1-R4	AFIN	16-00199
Photographer	Tobin Baker, Inspector			<i>TB</i>	Witness	N/A		
Photo #	2	Of	4		Date	1/12/2022	Time	1123
Description	Leachate discharge observed on the west slope of Cell 1.							
								

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199	
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A			
Photo #	3	Of	4		Date	1/12/2022		Time	1123	
Description	Leachate discharge observed on the west slope of Cell 1.									
										
Location	Craighead County SWDA Class 1				Permit	0254-S1-R4		AFIN	16-00199	
Photographer	Tobin Baker, Inspector				<i>TB</i>	Witness	N/A			
Photo #	4	Of	4		Date	1/12/2022		Time	1125	
Description	Leachate discharge observed on the west slope of Cell 1.									
										