

3/28/2022

Ms. Sarah Palazzi Albemarle Corporation P. O. Box 729 Magnolia, AR 71753-0729

RE: Inspection conducted on March 24, 2022

AFIN 14-00028

Permit Number 0251-S3N-R1

Dear Ms. Palazzi:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

Gerry Eddy

Solid Waste Inspector

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



Office of Land Resources Regulated Waste Operations Class 3 Landfill Inspection Form

Class 5 Landin Inspection I of in											
Site Name	Albemarle Corpo		3 Landfill	County		Columbia		AFIN		14-00028	
Facility Address 2270 Hwy 79 Ma					870-235-6000			rmit #	0251-S3N-R1		
Permittee Address P. O. Box 729 Magno			71753	Email Address			zzi@albemarle.)S #	119578	
Date	3/24/2022		Entry Time		0854		Ex	it Time	1000		
Operational Standards											
Category 1											
Regulation	Item Description					Comments					
522(a)	Annual Compliance Inspection by Registered Professional Engineer										
Category 2											
Regulation	Item Description					Comments					
510(a)	Operations in Accordance with Permit Documents										
516(c)	Adequate All Weather Operational Roads										
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face										
510(b)	Operations by Licensed On-site Operator at all Times										
510(d)	Waste Spread and Compacted as Unloaded										
518	Surface Water Control										
517(a)(b)	Run-on/off Control System Present and Adequate										
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation										
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation										
510(n)	Leachate Leaks or Evidence of Leachate Seepage										
526	Survey Controls										
529	Leachate Collection System										
Category 3											
Regulation	Item Description					Comments					
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover										
518	Cause Discharge/Leachate Discharge Leaving Landfill										
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse										
309(c)	Overfill/off Lined Area										
Records T/6/2021 Date of Last Operatory Methane Monitoring N/A											
Date of Last Annual			e Monitoring	N/A							
Date of Last Groundwater Monitoring Report2/15/2022Previous Quarter Waste Received299.13 Tons											
Operator Name & Number Steve L. Duggan 003534 Signature of Inspector											
Operator Name & N	number	Steve L. Dug Stephen Star		Signatur	Signature of Inspector						
	1 4 1 41			N/ 41 3	In Person		D 4	3/24/2022	-ady	Time 1000	
Exit Interview Conducted with		Stephen Stamps		Method	in Person		Date	3/24/2022		Time 1000	