



ARKANSAS

ENERGY & ENVIRONMENT

5/23/2022

Ms. Kelley Crouch
Domtar A. W. Corp.
285 Hwy. 71 South
Ashdown, AR 71822-0496

RE: Inspection conducted on May 10, 2022
AFIN 41-00002
Permit Number 0296-S3N

Dear Ms. Crouch:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or greenwood@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink, appearing to read 'Matthew Greenwood'.

Matthew Greenwood
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Domtar A.W. LLC Lime	County	Little River	AFIN	41-00002
Facility Address	Hwy. 71 S. of Ashdown	Phone #	870-898-2711 Ext 6172	Permit #	0296-S3N
Permittee Address	285 hwy. 71 South Ashdown, AR 71822-0496	Email Address	kelly.crouch@domtar.com	PDS #	120342
Date	05/10/22	Entry Time	0900	Exit Time	1100

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2

Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	June 2021	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	Feb 2022	Previous Quarter Waste Received	392

Operator Name & Number	Charles D. Schuetz 002943 Charles Allen	Signature of Inspector					
Exit Interview Conducted with	Charles Allen	Method	On-Site	Date	05/10/22	Time	1050