

8/15/2022

Mr. Robert Hendrix Craighead SWDA P.O. Box 16777 Jonesboro, AR 72403

**RE:** Inspection conducted on August 3, 2022

AFIN 16-00199

Permit Number 0013-TAP-TCC

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Used Tire Recycling and Accountability Act (Arkansas Code Annotated § 8-9-401, <u>et.seq.</u>) of 2017, as amended, and Arkansas Pollution Control & Ecology Commission (APC&EC) Rule No. 36, and the above referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-2097 or bakert@adeq.state.ar.us.

Sincerely,

**Tobin Baker** 

Solid Waste Inspector

Jobin Boker

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



## **Office of Land Resources** Regulated Waste Operations Tire Collection Center (TCC) Inspection Form

Site Name	Legacy Landfill TC		ection center	County		Craighead		AF	TNI	16-00199		
	238 CR 476 Jonesbo				v e		52			0013-TAP-TCC		
Facility Address			Phone #					rmit #				
Permittee Address	P.O. Box 16777, Jon	nesboro, AR 72403		Email Ac		rhendrix@c	<u>cswda.c</u>		S #	121362		
Date	8/3/2022		Entry Ti		0930		Ex	it Time	1145			
			Operation	ial Stanc	dards							
Category 1												
Regulation		escription				Comme	nts					
1505(A)	Recordkeeping											
1506(B)	1506(B) Monthly Inspection											
1508(C)	Signage											
1508(O)	1508(O) Emergency Prepa											
1509	Access Control											
1510	Vector Control											
	<u> </u>		Cat	tegory 2								
Regulation	Item D	escription Comments										
1508(K)	Run-on/run-off fo	r Tire Storage Area										
1508(L)	Fire Safety Surve	y										
1508(N)	Vegetation Aroun	d Tire Storage										
			Cat	tegory 3								
Regulation	Item D	Comments										
1508(A)	Storage Limits											
1508(D)	Tire Storage Dime	ensions										
1508(E)	Fire Lanes											
			R	ecords								
Date of Last Annual	<b>Date of Last Annual Report</b>		1/10/2022		<b>Previous Quarter Tires Received</b>			31,483				
<b>Date Last Shipment from the Facility</b>		8/3/2022		<b>Quantity of Tires Stored On-Site</b>			3,847					
<b>Previous Quarter Tires Shipped</b>		29,953										
									2 .			
Operator Name & Number		David Passmore 003246		Signature of Inspector			100 K	Booker				
Exit Interview Cond	lucted with	Robert Hendrix/David	Passmore	Method	On-site		Date	8/3/2022		<b>Time</b> 1140		

## Division of Environmental Quality Official Photograph Sheet

						0 1			
<b>Location</b> Leg <b>Photographer</b>		acy Lan	dfill Ti	ire Collection	Center	Permi	t 0013-TAP-TC	C AFIN	16-00199
		Tobin	Baker,	Inspector	TB	Witness	N/A		
Photo #	1	Of	1			Date	8/3/2022	Time	0955
Description	ì	Legacy	/ Landi	fill Tire Collec	ction Center	•		•	•