

9/22/2022

Ms. Sarah Palazzi Albemarle Corporation P. O. Box 729 Magnolia, AR 71753-0729

RE: Inspection conducted on September 20, 2022

AFIN 14-00028

Permit Number 0251-S3N-R1

Dear Ms. Palazzi:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

Gerry Eddy

Solid Waste Inspector

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



Office of Land Resources Regulated Waste Operations Class 3 Landfill Inspection Form

Site Name Albemarle Co		poration Class 3 Landfill		County		Columbia			AFIN	14-00028	
Facility Address 2270 Hwy 79 Ma		agnolia, AR		Phone #		870-235-6000			Permit #	0251-S3N-R1	
Permittee Address P. O. Box 729 Ma		agnolia, AR	71753	3 Email Address		Sarah.Palaz	zzi@albemarle.d	com	PDS#	122815	
Date 9/20/2022			Entry Time		me	0823			Exit Time	0931	
Operational Standards											
Category 1											
Regulation	Item Description					Comments					
522(a)	Annual Compliance Inspection by Registered Professional Engineer										
Category 2											
Regulation	Item Description					Comments					
510(a)	Operations in Accordance with Permit Documents										
516(c)	Adequate All Weather Operational Roads										
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face										
510(b)	Operations by Licensed On-site Operator at all Times										
510(d)	Waste Spread and C	Compacted as	Unloaded								
518	Surface Water Control										
517(a)(b)	Run-on/off Control System Present and Adequate										
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation										
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation										
510(n)	Leachate Leaks or Evidence of Leachate Seepage										
526	Survey Controls										
529	Leachate Collection System										
Category 3											
Regulation	Item Description						Com	ments			
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover										
518	Cause Discharge/Leachate Discharge Leaving Landfill										
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse										
309(c)	Overfill/off Lined Area										
Records											
							e Monitoring		/A		
Date of Last Groundwater Monitoring Report 8/15/2022 Previous Quarter Waste Received 346.15 Tons											
Special Control of Control			ephen Stamps 004197		Signature of Inspector Luny Eddy						
Exit Interview Cond	lucted with	Stephen Star	nps	Method	In Person		Date	9/20/202	2 / /	Time 0931	