



ARKANSAS

ENERGY & ENVIRONMENT

10/6/2022

Mr. Robert Sanchez
BFI Waste Systems of Arkansas
18511 W. Sardis Road
Bauxite, AR 72011

RE: Inspection conducted on September 26, 2022
AFIN 63-00155
Permit Number 0261-S1-R3

Dear Mr. Sanchez,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or Kimberly.Davenport@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport', is shown within a rectangular box.

Kim Davenport
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS

ENERGY & ENVIRONMENT

10/6/2022

Mr. Brad Zimmerman
BFI Waste Systems of Arkansas
5605 Moreau River Access Road
Jefferson City, MO 65101

RE: Inspection conducted on September 26, 2022
AFIN 63-00155
Permit Number 0261-S1-R3

Dear Mr. Zimmerman,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or Kimberly.Davenport@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink, appearing to read 'Kim Davenport', is shown above the printed name.

Kim Davenport
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	BFI Waste Systems of Arkansas	County	Saline	AFIN	63-00155
Facility Address	18511 W Sardis Road, Bauxite, AR	Phone #	901-873-8334 (Brad Zimmerman) 501-602-8440 (Robert Sanchez)	Permit #	0261-S1-R3
Permittee Address	18511 W Sardis Road, Bauxite, AR	Email Address	Bzimmerman2@republicservices.com RSanchez2@republicservices.com	PDS #	122977
Date	9/26/2022	Entry Time	1215	Exit Time	1400

Operational Standards

Category 1

Regulation	Item Description	Comments
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


Regulation	Item Description	Comments
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
411(o)	Leachate Leaks or Evidence of Leachate Seepage	
429	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2022	Date of Last Quarterly Methane Monitoring	6/1/2022
-----------------------------------	-----------	--	----------

Date of Last Groundwater Monitoring Report	6/29/2022	Previous Quarter Waste Received			80,028.39 Tons	
Operator Name & Number	Spencer Robbins- 003765	Signature of Inspector				
Exit Interview Conducted with	Robert Sanchez	Method	On-site	Date	9/26/2022	Time 1345