

10/27/2022

Mr. Cole Clark Elemental Environmental Solutions Gum Springs Hwy 67 South 500 E. Reynolds Road Arkadelphia, AR 71923-8817

RE: Inspection conducted on October 18, 2022

AFIN 10-00004

Permit Number 0262-S

Dear Mr. Clark:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or greenwood@adeq.state.ar.us.

Sincerely,

Matt Greenwood

Solid Waste Inspector

Mattle I

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



Office of Land Resources Regulated Waste Operations Class 3 Landfill Inspection Form

| Site Name | Elemental Environn | Elemental Environmental Solutions Class 3 Landfill | | | unty | Clark | | AFIN | 10-00004 |
|--|--|--|----------|-------------|--|--------------|----------|-----------|--------------------|
| Facility Address | 2 miles east of I-30 | 30 on Hwy. 26 East. | | Pho | one# | 870-245-2700 | | Permit # | 0262-S |
| Permittee Address | 500 E. Reynolds Rd | lphia, AR 71923 | Em | ail Address | cole.clark@v | olia.co | m PDS# | 123225 | |
| Date | 10/18/22 | | | Ent | try Time | 0900 | | Exit Time | 1000 |
| Operational Standards | | | | | | | | | |
| Category 1 | | | | | | | | | |
| Regulation | | Item | | Comments | | | | | |
| 522(a) | Annual Compliance I | neer | | | | | | | |
| | | | | | | | | | |
| Category 2 | | | | | | | | | |
| Regulation | | Item | | Comments | | | | | |
| 510(a) | Operations in Accord | | | | | | | | |
| 516(c) | Adequate All Weathe | | | | | | | | |
| 510(c) | Smallest Practical Area, Unloading Supervised, Single Working Face | | | | | | | | |
| 510(b) | Operations by Licens | | | | | | | | |
| 510(d) | Waste Spread and Co | mpacted a | | | | | | | |
| 518 | Surface Water Control | | | | | | | | |
| 517(a)(b) | Run-on/off Control S | | | | | | | | |
| 510(h)(2) | Surface Water Control Prevents Off-site Sediment Accumulation | | | | | | | | |
| 510(h)(i) | Adequate Maintenance of Intermediate/Final Cover Vegetation | | | | | | | | |
| 510(n) | Leachate Leaks or Ev | | | | | | | | |
| 526 | Survey Controls | | | | | | | | |
| 529 | Leachate Collection S | ystem | | | | | | | |
| | | | | | | | | | |
| Category 3 | | | | | | | | | |
| Regulation | Item Description | | | | Comments | | | | |
| 512(a)(b)(c) | Satisfactory Daily/Intermediate/Alternative Cover | | | | | | | | |
| 518 | Cause Discharge/Leachate Discharge Leaving Landfill | | | | | | | | |
| 510(n) | Erosion or Other Cover Defects Resulting in Exposed Refuse | | | | | | | | |
| 309(c) | Overfill/off Lined Arc | | | | | | | | |
| | | | | | | | | | |
| Records | | | | | | | | | |
| | | | | | of Last Quarterly Methane Monitoring N/A | | | | |
| Date of Last Groundwater Monitoring Report May 2022 Previous Quarter Waste Received N/A | | | | | | | | | |
| Special Control of Con | | | peration | | Signature of Inspector | | | lottes C | 10050 |
| Exit Interview Conducted with | | Cole Clark | | Method | On-Site | Da | te 10/ | 18/22 | Time 0950 |