



ARKANSAS

ENERGY & ENVIRONMENT

11/03/2022

Mr. Robert Hendrix
Craighead SWDA
P.O. Box 16777
Jonesboro, AR 72403

RE: Inspection conducted on October 13, 2022
AFIN 16-00923
Permit Number 0254-S1-R4

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-2097 or bakert@adeq.state.ar.us.

Sincerely,

A handwritten signature in cursive script that reads 'Tobin Baker'.

Tobin Baker
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Craighead County SWDA Class 1	County	Craighead	AFIN	16-00199
Facility Address	238 CR 476 Jonesboro, AR 72404	Phone #	870-972-6353	Permit #	0254-S1-R4
Permittee Address	P.O. Box 16777, Jonesboro AR 72403	Email Address	rhendrix@ccswda.com	PDS #	123308
Date	10/13/2022	Entry Time	0905	Exit Time	1045

Operational Standards

Category 1

Regulation	Item Description	Comments
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


Regulation	Item Description	Comments
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
411(o)	Leachate Leaks or Evidence of Leachate Seepage	
429	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/30/2022	Date of Last Quarterly Methane Monitoring	8/18/2022
Date of Last Groundwater Monitoring Report	7/15/2022	Previous Quarter Waste Received	Class 1- 26,269.94 Class 4-12,968.91

Operator Name & Number	Robert Hendrix 00336	Signature of Inspector					
Exit Interview Conducted with	Tim Mayne	Method	On-site	Date	10/13/2022	Time	1040

Division of Environmental Quality

Official Photograph Sheet

Location	Craighead County SWDA Class 1				Permit	0254-S1-R4	AFIN	16-00199
Photographer	Tobin Baker, Inspector			TB	Witness	N/A		
Photo #	1	Of	1		Date	10/13/2022	Time	1026
Description	A view of the Craighead County SWDA Class 1.							
								