



12/15/2022

Mr. Allen Thomas Green Bay Packaging, Inc. 338 Hwy. 113 Morrilton, AR 72110

## RE: Inspection conducted on December 9, 2022 AFIN 15-00001 Permit Number 0284-S3N

Dear Mr. Thomas,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 410-4462 or <u>daniel.cullum@adeq.state.ar.us</u>

Sincerely,

Daniel (ullum

Daniel Cullum Solid Waste Inspector 5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



## Office of Land Resources Regulated Waste Operations Class 3 Landfill Inspection Form

AND ENVIR		Class 5 Landi	in inspe	CUOII FOFI	1				
Site Name	te Name Green Bay Packaging Inc.		County		y Conway		15-00001		
Facility Address	338 Highway 113 Morrilton, AR 72110 P		Phone #	e # 501-334-9289		Permit #	0284-S3N		
Permittee Address	338 Highway 113 Morrilton, AR 72110 En		Email A	ddress	athomas@gbp.com	PDS #	123859		
Date	12/09/2022		Entry T	ime	1033	Exit Time	1159		
		Operatio							
		Ca	ategory 1						
Regulation	Item Description			Comments					
522(a)	Annual Compliance Inspection	by Registered Professional Eng	gineer						
			ategory 2		-				
Regulation		Description		Comments					
510(a)	Operations in Accordance with Permit Documents								
516(c)	Adequate All Weather Operational Roads								
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face								
510(b)	Operations by Licensed On-site	-							
510(d)	Waste Spread and Compacted	as Unloaded							
518	Surface Water Control								
517(a)(b)	Run-on/off Control System Pre	_							
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation								
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation								
<b>510(n)</b>	Leachate Leaks or Evidence of Leachate Seepage								
526	Survey Controls								
529	Leachate Collection System								
			-4						
Regulation	Category 3   Item Description Comments								
512(a)(b)(c)		Satisfactory Daily/Intermediate/Alternative Cover			Commen	13			
512(a)(b)(c)	Cause Discharge/Leachate Discharge Leaving Landfill								
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse								
309(c)	Overfill/off Lined Area								
		]	Records						
Date of Last Annual Report		05/13/2022	Date of	Last Quarter	ly Methane Monitoring	NA			
Date of Last Groun	dwater Monitoring Report	06/09/2022	Previou	s Quarter Wa	53,914.70 Cubic	Yards			

Operator Name & Number	Allen Thomas-004042 Jacob Wesson-004582	Signatur	e of Inspector		Daniel Cul	lum	
Exit Interview Conducted with	Jacob Wesson	Method	On Site	Date	12/09/2022	Time	1152