



# ARKANSAS

## ENERGY & ENVIRONMENT

12/15/2022

Brandon Bradberry  
Plant Manager  
Entergy Independence SES  
555 Point Ferry Road  
Newark, AR 72562

**RE: Inspection conducted on December 5, 2022**  
**AFIN 32-00042**  
**Permit Number 0200-S3N-R2**

Dear Mr. Bradberry:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or [darrell.norton@adeq.state.ar.us](mailto:darrell.norton@adeq.state.ar.us)

Sincerely,

A handwritten signature in cursive script that reads 'Darrell Norton'.

Darrell Norton  
Solid Waste Inspector  
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



**ARKANSAS**  
ENERGY & ENVIRONMENT

**Office of Land Resources  
Regulated Waste Operations  
Class 3 Landfill Inspection Form**

<b>Site Name</b>	Entergy- Independence Plant	<b>County</b>	Independence	<b>AFIN</b>	32-00042
<b>Facility Address</b>	555 Point Ferry , Newark, AR 72562	<b>Phone #</b>	870-799-8761 Entergy 870-799-3565	<b>Permit #</b>	0200-S3N-R2
<b>Permittee Address</b>	555 Point Ferry , Newark, AR 72562	<b>Email Address</b>	<a href="mailto:Awilsol@entergy.com">Awilsol@entergy.com</a>	<b>PDS #</b>	123872
<b>Date</b>	12/5/2022	<b>Entry Time</b>	1040	<b>Exit Time</b>	1150

**Operational Standards**

**Category 1**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

**Category 2**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

**Category 3**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

**Records**

<b>Date of Last Annual Report</b>	6/29/2022	<b>Date of Last Quarterly Methane Monitoring</b>	N/A
<b>Date of Last Groundwater Monitoring Report</b>	3/7/2022	<b>Previous Quarter Waste Received</b>	145168.95 tons. Includes pond waste

<b>Operator Name &amp; Number</b>	Patrick Davenport 004564 (A) Phillip Fick Jr.004049(C)	<b>Signature of Inspector</b>	<i>Darrell Norton</i>
-----------------------------------	---	-------------------------------	-----------------------

<b>Exit Interview Conducted with</b>	Patrick Davenport	<b>Method</b>	In person	<b>Date</b>	12/5/2022	<b>Time</b>	1140
--------------------------------------	-------------------	---------------	-----------	-------------	-----------	-------------	------

## Division of Environmental Quality Official Photograph Sheet

<b>Location</b>	Entergy-Independence Plant			<b>Permit</b>	0200-S3N-R2	<b>AFIN</b>	32-00042
<b>Photographer</b>	Darrell Norton , Inspector		<i>DN</i>	<b>Witness</b>	Patrick Davenport, facility operator		
<b>Photo #</b>	1	<b>Of</b>	2	<b>Date</b>	12/5/2022	<b>Time</b>	1054
<b>Description</b>	A view of recently completed slope stabilization on the south side of Cell 15.						



<b>Location</b>	Entergy-Independence Plant			<b>Permit</b>	0200-S3N-R2	<b>AFIN</b>	32-00042
<b>Photographer</b>	Darrell Norton, Inspector		<i>DN</i>	<b>Witness</b>	Patrick Davenport, facility operator.		
<b>Photo #</b>	2	<b>Of</b>	2	<b>Date</b>	12/5/2022	<b>Time</b>	1056
<b>Description</b>	A view of recently completed work to Cell 15.						

