

12/22/2022

Jerry Coleman General Manager BFI Waste Systems of Arkansas 1911 W 65th St Little Rock, AR 72209

RE: Inspection conducted on December 7, 2022

AFIN 63-00155

Permit Number 0277-S4

Dear Mr. Coleman,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or Kimberly.Davenport@adeq.state.ar.us

Sincerely,

Kim Davenport

Solid Waste Inspector

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



Office of Land Resources Regulated Waste Operations Class 4 Landfill Inspection Form

| Site Name | BFI Waste Systems of Arkansas, LLC- Class 4 | County | | Saline | AFIN | 63-00155 |
|--------------------|---|-------------------|-------|---|-----------|----------|
| Facility Address | 18511 W. Sardis, Bauxite, AR 72011 | Phone # | | 859-227-3861 (Jerry Coleman) 901-873-8334 (Brad Zimmerman) | Permit # | 0277-S4 |
| Permittee | 18511 W. Sardis, Bauxite, AR 72011 | Email Addre | ess | Jcoleman2@republicservices.com | PDS# | 123937 |
| Address | | | | Bzimmerman2@republicservices.com | | |
| Date | 12/7/2022 | Entry Time | | 1215 | Exit Time | 1530 |
| | Op | erational St | tanda | ards | | |
| | | Category | 1 | | | |
| Regulation | Item Description | | | Comments | | |
| 617(a)(b) | Record Keeping Requirements Specified by Regulation | <u>.</u> | | | | |
| 607(j) | Adequate Provisions for Backup Equipment | | | | | |
| 619 | Annual Compliance Inspection by Registered Professio | nal Engineer | | | | |
| | | Category | 2 | | | |
| Regulation | Item Description | Category | 4 | Comments | | |
| 607(a) | Operations in Accordance with Permit Documents | | | | | |
| 613(c) | Adequate All Weather Operational Roads | | | | | |
| 607(c)(d) | Smallest Practical Area, Single Working Face | | | | | |
| 607(b) | Operations by Licensed On-site Personnel at All Times | | | | | |
| 607(g) | Litter Control Provisions Maintained | | | | | |
| 622 | Survey Controls | | | | | |
| 623 | Surface Water Controls | | | | | |
| 607(h)(1) | Contouring Prevents Surface Water Flowing Into or Th | rough Waste | | | | |
| 607(h)(2) | Surface Water Control Prevents Off-site Sediment Acc | umulation | | | | |
| 607(i)(o) | Adequate Maintenance of Intermediate/Final Cover Vegetation | | | | | |
| 607(o) | Leachate Leaks or Evidence of Leachate Seepage | | | | | |
| | | Category | 3 | | | |
| Regulation | Item Description | Category | 3 | Comments | | |
| 608 | Implementation of Hazardous Waste Exclusion Plan | | | | | |
| 609(a) | Satisfactory Weekly or More Frequent Cover | | | | | |
| 609(b) | Satisfactory Immediate Cover | | | | | |
| 615 | Cause Discharge/Leachate Discharge Leaving Landfill | | | | | |
| 607(o) | Erosion or Other Cover Defects Resulting in Exposed Refuse | | | | | |
| 309(c) | Overfill/Off Lined Area | | | | | |
| | | | | | | |
| D. A. GT. A. A. | 2/21/2022 | Records | | | | |
| Date of Last Annua | al Report 3/31/2022 | Date of Last | Quar | terly Methane Monitoring N | /A | |

| Date of Last Groundwater Monitor | ing Report N/A | Previous Quarter Waste Received | 0 |
|---|-----------------|--|--|
| | | | |
| Operator Name & Number | Closed facility | Signature of Inspector | Hans |
| Exit Interview Conducted with | Jerry Coleman | Method On-site | Date 12/7/2022 Time 1500 |