



ARKANSAS ENERGY & ENVIRONMENT

3/23/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q1 Follow-up #7 conducted on March 15, 2023
AFIN 72-00144
Permit Number 0290-S4-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads 'Gerry Eddy'.

Gerry Eddy
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 4 Landfill Inspection Form**

Site Name	Eco-Vista Class 4 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S4-R2
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS #	125067
Date	03/15/23	Entry Time	1044	Exit Time	1405

Operational Standards

Category 1

Regulation	Item Description	Comments
617(a)(b)	Record Keeping Requirements Specified by Regulations	
607(j)	Adequate Provisions for Backup Equipment	
619	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
607(a)	Operations in Accordance with Permit Documents	
613(c)	Adequate All Weather Operational Roads	
607(c)(d)	Smallest Practical Area, Single Working Face	
607(b)	Operations by Licensed On-site Personnel at All Times	
607(g)	Litter Control Provisions Maintained	
622	Survey Controls	
623	Surface Water Controls	
607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
607(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
607(i)(o)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
607(o)	Leachate Leaks or Evidence of Leachate Seepage	

Category 3

Regulation	Item Description	Comments
608	Implementation of Hazardous Waste Exclusion Plan	
609(a)	Satisfactory Weekly or More Frequent Cover	
609(b)	Satisfactory Immediate Cover	
615	Cause Discharge/Leachate Discharge Leaving Landfill	
607(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	

Records

Date of Last Annual Report	3/31/2022	Date of Last Quarterly Methane Monitoring	11/16/2022
Date of Last Groundwater Monitoring Report	11/29/2022	Previous Quarter Waste Received	31,934.23 Tons

Operator Name & Number	Don Tennison 2769	Signature of Inspector					
Exit Interview Conducted with	Don Tennison and Blake Small	Method	On-site	Date	03/15/23	Time	1405