



3/27/2023

Mr. Blake Small Eco-Vista, LLC 2210 Waste Management Drive Springdale, AR 72762

RE: Q1 Follow-up #8 conducted on March 21, 2023 AFIN 72-00144 Permit Number 0290-84-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us.

Sincerely,

Jason Gilkey Solid Waste Inspector 5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS ENERGY & ENVIRONMENT

Office of Land Resources Regulated Waste Operations Class 4 Landfill Inspection Form

Class 4 Landfill Inspection Form										
Site Name	Eco-Vista Class 4 Landfill		County	Washington	AFIN	72-00144				
Facility Address	2210 Waste Management Dr	ive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S4-R2				
Permittee Address	2210 Waste Management Dr	ive, Springdale, AR 72762	Email Address	bsmall@wm.com	PDS #	125087				
Date	3/21/2023		Entry Time	0933	Exit Time	1320				
		Operation	al Standards							
		Cat	egory 1							
Regulation	Item I	Description		Comments						
617(a)(b)	Record Keeping Requirements	Specified by Regulations								
607(j)	Adequate Provisions for Backu	p Equipment								
619	Annual Compliance Inspection by Registered Professional Engineer									
		Cat	egory 2							
Regulation		Description		Comments						
607(a)	Operations in Accordance with	Permit Documents								
613(c)	Adequate All Weather Operation									
607(c)(d)	Smallest Practical Area, Single									
607(b)	Operations by Licensed On-site	Personnel at All Times								
607(g)	Litter Control Provisions Main	tained								
622	Survey Controls									
623	Surface Water Controls									
607(h)(1)	Contouring Prevents Surface W	ater Flowing Into or Through W	aste							
607(h)(2)	Surface Water Control Prevent	s Off-site Sediment Accumulation	1							
607(i)(o)	Adequate Maintenance of Inter	mediate/Final Cover Vegetation								
607(o)	Leachate Leaks or Evidence of	Leachate Seepage								
		Cat	egory 3							
Regulation		Description		Comments						
608	Implementation of Hazardous									
609(a)	Satisfactory Weekly or More Fi	requent Cover								
609(b)	Satisfactory Immediate Cover									
615	Cause Discharge/Leachate Disc	8								
607(o)	Erosion or Other Cover Defects	Resulting in Exposed Refuse								
309(c)	Overfill/Off Lined Area									
			ecords							
Dute of East Annual Report		3/31/2022		terly Methane Monitoring	11/16/2022					
Date of Last Groundwater Monitoring Report11/29/2022Previous Quarter Waste Received31,934.23 Tons										

Operator Name & Number	Don Tennison 2769	Signature of Inspector		Jacon C. Silkey		
Exit Interview Conducted with	Don Tennison	Method On-site	Date	3/21/2023	Time	1315