

3/28/2023

Ms. Sarah Palazzi Albemarle Corporation P. O. Box 729 Magnolia, AR 71753-0729

RE: Inspection conducted on March 21, 2023

AFIN 14-00028

Permit Number 0251-S3N-R1

Dear Ms. Palazzi:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us.

Sincerely,

Gerry Éddy

Solid Waste Inspector

5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



Office of Land Resources Regulated Waste Operations Class 3 Landfill Inspection Form

			Clubb C Eu	ilaili ili	pection	1 01111					
Site Name	Albemarle Corpo	arle Corporation Class 3 Landfill			County		Columbia		AFIN	14-00028	
Facility Address	2270 Hwy 79 Ma	agnolia, AR	nolia, AR P		Phone #		870-235-6000		Permit #	0251-S3N-R1	
Permittee Address P. O. Box 729 Magnolia, AR 7			R 71753	Email Address		Sarah.Palazzi@albemarle.com		.com	PDS#	125122	
Date 3/21/.2023				Entry Time		0900			Exit Time	1010	
Operational Standards											
Category 1											
Regulation		Comments									
522(a)	Item Description Annual Compliance Inspection by Registered Professional Engineer										
Category 2											
Regulation	Item Description					Comments					
510(a)	Operations in Accordance with Permit Documents										
516(c)	Adequate All Weather Operational Roads										
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face										
510(b)	Operations by Licensed On-site Operator at all Times										
510(d)	Waste Spread and Compacted as Unloaded										
518	Surface Water Control										
517(a)(b)	Run-on/off Control System Present and Adequate										
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation										
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation										
510(n)	Leachate Leaks or l	Evidence of L	eachate Seepage								
526	Survey Controls										
529	Leachate Collection System										
Category 3											
Regulation	Item Description					Comments					
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover										
518	Cause Discharge/Leachate Discharge Leaving Landfill										
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse										
309(c)	Overfill/off Lined Area										
Records											
Date of Last Annual Report 6/30/2022					-		e Monitoring		I/A		
Date of Last Groundwater Monitoring Report 3/17/2023 Previous Quarter Waste Received 681.68 Tons											
Operator Name & Number Stephen Stamps 004197 Signature of Inspector											
Operator Name & Number Stephen Stamps 004197 Signature of Inspector							A	Eddy			
Evit Interview Cone	duated with	Stephen Stamps		Method	In Person		Date	3/21/202	/	Time 1010	
Exit Interview Cond	aucteu with	Stephen Stamps		Method	111 1 013011		Date	31211202	/	1 IIIIe 1010	