



ARKANSAS ENERGY & ENVIRONMENT

3/31/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q1 Follow-up #10 conducted on March 24, 2023
AFIN 72-00144
Permit Number 0290-S4-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-8186 or richard.goheen@adeq.state.ar.us.

Sincerely,

A handwritten signature in blue ink that reads "Richard Goheen". The signature is written in a cursive style.

Richard Mason Goheen
Solid Waste Inspector Supervisor
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 4 Landfill Inspection Form**

| | | | | | |
|--------------------------|---|----------------------|--|------------------|-------------|
| Site Name | Eco-Vista Class 4 Landfill | County | Washington | AFIN | 72-00144 |
| Facility Address | 2210 Waste Management Drive, Springdale, AR 72762 | Phone # | 870-510-0174 | Permit # | 0290-S4-R2 |
| Permittee Address | 2210 Waste Management Drive, Springdale, AR 72762 | Email Address | bsmall@wm.com dtenniso@wm.com | PDS # | 125172 |
| Date | 03/24/2023 | Entry Time | 0430 & 0730 | Exit Time | 0630 & 0856 |

Operational Standards

Category 1

| Regulation | Item Description | Comments |
|-------------------|--|-----------------|
| 617(a)(b) | Record Keeping Requirements Specified by Regulations | |
| 607(j) | Adequate Provisions for Backup Equipment | |
| 619 | Annual Compliance Inspection by Registered Professional Engineer | |

Category 2

| Regulation | Item Description | Comments |
|-------------------|---|-----------------|
| 607(a) | Operations in Accordance with Permit Documents | |
| 613(c) | Adequate All Weather Operational Roads | |
| 607(c)(d) | Smallest Practical Area, Single Working Face | |
| 607(b) | Operations by Licensed On-site Personnel at All Times | |
| 607(g) | Litter Control Provisions Maintained | |
| 622 | Survey Controls | |
| 623 | Surface Water Controls | |
| 607(h)(1) | Contouring Prevents Surface Water Flowing Into or Through Waste | |
| 607(h)(2) | Surface Water Control Prevents Off-site Sediment Accumulation | |
| 607(i)(o) | Adequate Maintenance of Intermediate/Final Cover Vegetation | |
| 607(o) | Leachate Leaks or Evidence of Leachate Seepage | |

Category 3

| Regulation | Item Description | Comments |
|-------------------|--|-----------------|
| 608 | Implementation of Hazardous Waste Exclusion Plan | |
| 609(a) | Satisfactory Weekly or More Frequent Cover | |
| 609(b) | Satisfactory Immediate Cover | |
| 615 | Cause Discharge/Leachate Discharge Leaving Landfill | |
| 607(o) | Erosion or Other Cover Defects Resulting in Exposed Refuse | |
| 309(c) | Overfill/Off Lined Area | |

Records

| | | | |
|---|------------|--|----------------|
| Date of Last Annual Report | 3/31/2022 | Date of Last Quarterly Methane Monitoring | 11/16/2022 |
| Date of Last Groundwater Monitoring Report | 11/29/2022 | Previous Quarter Waste Received | 31,934.23 Tons |

| | | | | | | | |
|--------------------------------------|-------------------|-------------------------------|---------|-------------|---------------|-------------|------|
| Operator Name & Number | Don Tennison 2769 | Signature of Inspector | | | Richard Cohen | | |
| Exit Interview Conducted with | Don Tennison | Method | On-site | Date | 03/24/2023 | Time | 0856 |