



ARKANSAS ENERGY & ENVIRONMENT

04/18/2023

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Q2 Follow-up #1 conducted on April 6, 2023
AFIN 72-00144
Permit Number 0290-S1-R3

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 258-3144 or daniel.cullum@adeq.state.ar.us

Sincerely,

A handwritten signature in blue ink that reads "Daniel Cullum". The signature is written in a cursive, flowing style.

Daniel Cullum
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources



ARKANSAS
ENERGY & ENVIRONMENT

**Office of Land Resources
Regulated Waste Operations
Class 1 Landfill Inspection Form**

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R3
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com	PDS #	125377
Date	04/06/2023	Entry Time	1227	Exit Time	1412

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	


Category 2

	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
	411(o)	Leachate Leaks or Evidence of Leachate Seepage	
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	413(a)	Satisfactory Daily Cover	
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2023	Date of Last Quarterly Methane Monitoring			1/9/2023		
Date of Last Groundwater Monitoring Report	2/28/2023	Previous Quarter Waste Received			166,344.67 Tons		
Operator Name & Number	Don Tennison -2769		Signature of Inspector				
Exit Interview Conducted with	Don Tennison	Method	On Site	Date	04/06/2023	Time	1408