

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

6/22/2023

Ms. Sarah Palazzi Albemarle Corporation P. O. Box 729 Magnolia, AR 71753-0729

RE: Inspection conducted on June 20, 2023 AFIN 14-00028

Permit Number 0251-S3N-R1

Dear Ms. Palazzi,

The Arkansas Division of, Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6916 or eddy@adeq.state.ar.us

Sincerely,

Gerry Eddy

Duny Eddy

Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

Division of Environmental Quality Office of Land Resources Class 3 Landfill Inspection Form

	T		Class 3 La		spection			T	T	
Site Name Albemarle Corporation Class 3			•		Columbia		AFIN	14-00028		
Facility Address 2270 Hwy 79 Magnolia,				Phone #		870-235-6000		Permit #	0251-S3N-R1	
Permittee Address P. O. Box 729 Magnolia, AR			71753	Email Address		Sarah.Palazzi@albemarle.com		PDS#	126347	
Date 6/20/2023				Entry Time		0835		Exit Time	0940	
Operational Standards										
			y 1							
Regulation	Item Description					Comments				
522(a)	Annual Compliance Inspection by Registered Professional Engineer									
Category 2										
Regulation	Item Description					Comments				
510(a)	Operations in Accordance with Permit Documents									
516(c)	Adequate All Weather Operational Roads									
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face									
510(b)	Operations by Licensed On-site Operator at all Times									
510(d)	Waste Spread and Compacted as Unloaded									
518	Surface Water Control									
517(a)(b)	Run-on/off Control System Present and Adequate									
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation									
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation									
510(n)	Leachate Leaks or Evidence of Leachate Seepage									
526	Survey Controls									
529	Leachate Collection System									
				Category	y 3					
Regulation	Item Description				Comments					
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover									
518	Cause Discharge/Leachate Discharge Leaving Landfill									
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse									
309(c)	Overfill/off Lined Area									
Records										
Date of East Himaai Report			6/30/2022		Date of Last Quarterly Methane Monitoring N/A Previous Quarter Waste Received 297.86 Tons					
Date of Last Groundwater Monitoring Report 3/17/2023 Previous						Vaste Received		297.86 Tons		
Operator Name & Number Stephen			en Stamps 004197 Signatur		re of Inspector			my Eddy		
Exit Interview Conducted with Step			nps	Method	In Person	Da		0/2023	Time 0940	
						<u>_</u>	1		<u> </u>	