

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

8/3/2023

Mr. Blake Small Eco-Vista, LLC 2210 Waste Management Drive Springdale, AR 72762

RE: Inspection conducted on July 26, 2023

AFIN 72-00144

Permit Number 0290-S1-R4

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us

Sincerely,

Jason Gilkey

Solid Waste Inspector

Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

Division of Environmental Quality
Office of Land Resources
Class 1 Landfill Inspection Form

	Class 1 Landfi	ll Inspection Fo	orm			
ite Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144	
acility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R4	
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS#	126884	
ate	7/26/2023	Entry Time	1240	Exit Time	1510	
	Operation	nal Standards				
		tegory 1				
Regulation	Item Description					
417	Access Requirements					
411(j)	Adequate Provision for Backup Equipment					
423(b)	Annual Compliance Inspection by Registered Engineer					
	Car	tegory 2				
Regulation	Item Description		Commer	ıts		
411(a)	Operations in Accordance with Permit Documents					
411(c)	Smallest Practical Area, Unloading Supervised, Single Working	Face				
411(b)	Operations by Licensed On-site Personnel at All Times					
411(g)	Litter Control Provisions Maintained					
427	Surface Water Controls					
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through W	/aste				
418(a)(b)	Run-on/off Control System Present and Adequate					
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	n				
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation					
415	Gas Monitoring Program					
411(o)	Leachate Leaks or Evidence of Leachate Seepage					
429	Leachate Collection System					
Degulation	Item Description	tegory 3	Commer	•4a		
Regulation 413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover		Commer	its		
419(a)(5)	Cause Discharge/Leachate Leaving Landfill					
411(f)(3)	Depositing Waste in Standing Water Prohibited					
411(0)	Erosion or Other Cover Defects Resulting in Exposed Refuse					
309(c)	Overfill/Off Lined Area					
007(0)	S. S. M. S.					
	R	ecords				
ate of Last Annual			terly Methane Monitoring	6/8/2023		

2/28/2023

Date of Last Groundwater Monitoring Report

Previous Quarter Waste Received

135,996.38 Tons

Operator Name & Number	Don Tennison 02769	Signatur	e of Inspector		Jacon C. Silkey						
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	7/26/2023	Time	1505				