

DIVISION OF ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

8/3/2023

Mr. Blake Small Eco-Vista, LLC 2210 Waste Management Drive Springdale, AR 72762

RE: Inspection conducted on July 26, 2023

AFIN 72-00144

Permit Number 0290-S4-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us.

Sincerely,

Jason Gilkey

Solid Waste Inspector

Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

Division of Environmental Quality
Office of Land Resources
Class 4 Landfill Inspection Form

		Class 4 Landfi	ll Ins	pection Fo	· m		
Site Name	Eco-Vista Class 4 Landfill		Cour	1	Washington	AFIN	72-00144
Facility Address			Phor		870-510-0174	Permit #	0290-S4-R2
Permittee Address	2210 Waste Management Dr		+	il Address	bsmall@wm.com dtenniso@wm.com	PDS #	126885
Date	7/26/2023		Entry Time		1240	Exit Time	1510
		Operation	ıal Sı	tandards			
			tegory				
Regulation	Item 1	Description	<u>g</u> <u>J</u>		Comme	nts	
617(a)(b)	Record Keeping Requirements						
607(j)	Adequate Provisions for Backu	p Equipment					
619	Annual Compliance Inspection	by Registered Professional Engir	neer				
_		Cat	tegory	2			
Regulation	Item 1	Description			Comme	nts	
607(a)	Operations in Accordance with Permit Documents						
613(c)	Adequate All Weather Operati	onal Roads					
607(c)(d)	Smallest Practical Area, Single	Working Face					
607(b)	Operations by Licensed On-site	Personnel at All Times					
607(g)	Litter Control Provisions Main	tained					
622	Survey Controls						
623	Surface Water Controls						
607(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste						
607(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation						
607(i)(o)	Adequate Maintenance of Intermediate/Final Cover Vegetation						
607(o)	Leachate Leaks or Evidence of Leachate Seepage						
	-		tegory	3			
Regulation		Description			Comme	nts	
608	Implementation of Hazardous Waste Exclusion Plan						
609(a)	Satisfactory Weekly or More Frequent Cover						
609(b)	Satisfactory Immediate Cover						
615	Cause Discharge/Leachate Discharge Leaving Landfill						
607(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse						
309(c) Overfill/Off Lined Area							
		n	ecords				
Date of Last Annual	Panart	3/31/2023			erly Methane Monitoring	6/8/2023	
	Iwater Monitoring Report	2/28/2023	Date	or Last Quar	erry premiane promioring	37,597.37 Tons	

Operator Name & Number	Don Tennison 02769	Signatur	e of Inspector		Zacon C. Lilkey								
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	7/26/2023	Time	1505						