

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

8/16/2023

The Honorable Woody Wheeless Crittenden County Judge 100 Court Square Marion, AR 72364

RE: Inspection conducted on August 8, 2023

AFIN 18-00094

Permit Number 0245-S1-R2

Dear Judge Wheeless,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-2097 or Tobin.Baker@adeq.state.ar.us

Sincerely,

Tobin Baker

Solid Waste Inspector

Jobin Baker

cc: Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

Division of Environmental Quality Office of Land Resources Class 1 Landfill Inspection Form

	Class 1 Landfill Inspection Form										
Site Name Crittenden County Class 1			County	Crittenden	AFIN	18-00094					
Facility Address 1299 Khun Rd. West Memphis, AR 72301		Phone #	LF: 870-732-4290 Off: 870-732-6580	Permit #	0245-S1-R2						
Permittee Address	100 Court Street Marion, AR 723	64	Email Addres	is judgewheeless@crittco.com	PDS#	127036					
Date	8/8/2023		Entry Time	1005	Exit Time	1120					
Operational Standards											
Category 1											
Regulation	Item Description			Comments							
417	Access Requirements										
411(j)	Adequate Provision for Backup Equipment										
423(b)	Annual Compliance Inspection by Registered Engineer										
Category 2											
Regulation	Item Description			Comments							
411(a)	Operations in Accordance with Permit Documents										
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face										
411(b)	Operations by Licensed On-site Personnel at All Times										
411(g)	Litter Control Provisions Maintained										
427	Surface Water Controls										
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste										
418(a)(b)	Run-on/off Control System Present and Adequate										
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation										
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation										
415	Gas Monitoring Program										
411(0)	Leachate Leaks or Evidence of Leachate Seepage										
429	Leachate Collection System										
			Catego								
Regulation	Item Description			Comments							
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover										
419(a)(5)	Cause Discharge/Leachate Leaving Landfill										
411(f)(3)	Depositing Waste in Standing Water Prohibited										
411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse										
309(c)	Overfill/Off Lined Area										
			-								
Records											
				te of Last Quarterly Methane Monitoring	7/17/2023 46,757.04						
Date of Last Groundwater Monitoring Report		/2023	Pr	Previous Quarter Waste Received 40							

Operator Name & Number	Ed Jackson- 001217	Signature of Inspector		Jobin Boker	
Exit Interview Conducted with	Josh Kirkpatrick	Method On-site	Date	8/8/2023	Time 1115