



DIVISION OF
ENVIRONMENTAL QUALITY

127251

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

8/29/2023

Brandon Bradberry
Plant Manager
Entergy Independence SES
555 Point Ferry Road
Newark, AR 72562

RE: Inspection conducted on August 24, 2023
AFIN 32-00042
Permit Number 0200-S3N-R2

Dear Mr. Bradberry,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or darrell.norton@adeq.state.ar.us

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector

cc: Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

| | | | | | |
|--------------------------|------------------------------------|----------------------|--|------------------|-------------|
| Site Name | Entergy- Independence Plant | County | Independence | AFIN | 32-00042 |
| Facility Address | 555 Point Ferry , Newark, AR 72562 | Phone # | 870-799-8761 Entergy 870-799-3565 | Permit # | 0200-S3N-R2 |
| Permittee Address | 555 Point Ferry, Newark, AR 72562 | Email Address | Awilsol@entergy.com | PDS # | 127251 |
| Date | 8/24/2023 | Entry Time | 0910 | Exit Time | 1010 |

Operational Standards

Category 1

| | Regulation | Item Description | Comments |
|--|------------|--|----------|
| | 522(a) | Annual Compliance Inspection by Registered Professional Engineer | |

Category 2


| | Regulation | Item Description | Comments |
|--|------------|--|----------|
| | 510(a) | Operations in Accordance with Permit Documents | |
| | 516(c) | Adequate All Weather Operational Roads | |
| | 510(c) | Smallest Practical Area, Unloading Supervised, Single Working Face | |
| | 510(b) | Operations by Licensed On-site Operator at all Times | |
| | 510(d) | Waste Spread and Compacted as Unloaded | |
| | 518 | Surface Water Control | |
| | 517(a)(b) | Run-on/off Control System Present and Adequate | |
| | 510(h)(2) | Surface Water Control Prevents Off-site Sediment Accumulation | |
| | 510(h)(i) | Adequate Maintenance of Intermediate/Final Cover Vegetation | |
| | 510(n) | Leachate Leaks or Evidence of Leachate Seepage | |
| | 526 | Survey Controls | |
| | 529 | Leachate Collection System | |

Category 3

| | Regulation | Item Description | Comments |
|--|--------------|--|----------|
| | 512(a)(b)(c) | Satisfactory Daily/Intermediate/Alternative Cover | |
| | 518 | Cause Discharge/Leachate Discharge Leaving Landfill | |
| | 510(n) | Erosion or Other Cover Defects Resulting in Exposed Refuse | |
| | 309(c) | Overfill/off Lined Area | |

Records

| | | | |
|---|-----------|--|--------------|
| Date of Last Annual Report | 6/19/2023 | Date of Last Quarterly Methane Monitoring | n/a |
| Date of Last Groundwater Monitoring Report | 12/1/2022 | Previous Quarter Waste Received | 5980.99 tons |

| | | | |
|--------------------------------------|---|-------------------------------|---|
| Operator Name & Number | Patrick Davenport 004564 (B) Brian Malone 001499 (C) | Signature of Inspector |  |
| Exit Interview Conducted with | Patrick Davenport | Method | In person |
| | | Date | 8/24/2023 |
| | | Time | 1000 |

Division of Environmental Quality Official Photograph Sheet

| | | | | | | | |
|---------------------|---|-----------|-----------|----------------|--------------------------------------|-------------|----------|
| Location | Entergy-Independence Plant | | | Permit | 0200-S3N-R2 | AFIN | 32-00042 |
| Photographer | Darrell Norton , Inspector | | <i>DN</i> | Witness | Patrick Davenport, Facility operator | | |
| Photo # | 1 | Of | 2 | Date | 8/24/2023 | Time | 0931 |
| Description | A view of cells 15, 12, 11 and 8, with slope stabilization completed. | | | | | | |



| | | | | | | | |
|---------------------|--|-----------|-----------|----------------|---------------------------------------|-------------|----------|
| Location | Entergy-Independence Plant | | | Permit | 0200-S3N-R2 | AFIN | 32-00042 |
| Photographer | Darrell Norton, Inspector | | <i>DN</i> | Witness | Patrick Davenport, Facility operator. | | |
| Photo # | 2 | Of | 2 | Date | 8/24/2023 | Time | 0931 |
| Description | A view of the working face in cell 15. | | | | | | |

