

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

11/6/2023

Mr. Cole Clark Elemental Environmental Solutions Gum Springs Hwy 67 South 500 E. Reynolds Road Arkadelphia, AR 71923-8817

RE: Inspection conducted on October 25, 2023 AFIN 10-00004

Permit Number 0262-S

Dear Mr. Clark:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or matthew.greenwood@arkansas.gov.

Sincerely,

Mattle Lan

Matt Greenwood Solid Waste Inspector

cc: Heath Cobb, Senior Compliance Manager, Regulated Waste Operations

Division of Environmental Quality Office of Land Resources Class 3 Landfill Inspection Form

Elemental Environmenta	1 C 1 . C1 2 T 1C11	I					
	al Solutions Class 3 Landfill	Cour		Clark		AFIN	10-00004
2 miles east of I-30 on H	wy. 26 East.	Phon	ne #	870-245-2700)	Permit #	0262-S
500 E. Reynolds Rd. Ark	kadelphia, AR 71923	Emai	il Address	cole.clark@ve	eolia.con	PDS#	128169
10/25/23		Entr	y Time	1000		Exit Time	1100
	Operationa	al Standa	ards				
Item Description			Comments				
Annual Compliance Inspec	etion by Registered Professional Engine	per er					
		gory 2					
Item Description			Comments				
•							
•							
Waste Spread and Compacted as Unloaded							
Surface Water Control							
Run-on/off Control System Present and Adequate							
Surface Water Control Prevents Off-site Sediment Accumulation							
Adequate Maintenance of Intermediate/Final Cover Vegetation							
Leachate Leaks or Evidence of Leachate Seepage							
Survey Controls							
Leachate Collection System							
		gory 3					
					Comme	nts	
<u> </u>							
Overfill/off Lined Area							
	Th.						
I Dan aut			«4 O41	Ma4ha N#		N/A	
ate of East Himaar Report			are of East Quarterly internant monitoring				
iwater Monitoring Repo	August 2023	rrevious (zuarter was	ste Keceivea		11/71	
Number Not	in Operation	Signature :	of Inspector	•	1	16.	
Tullinoi		Signature of inspector			Md	the state of the s	
Jucted with Col	e Clark	Method	On-Site	De	te 10/2	5/23	Time 1050
	500 E. Reynolds Rd. Ari 10/25/23 It Annual Compliance Inspect Adequate All Weather Ope Smallest Practical Area, Un Operations by Licensed On Waste Spread and Compact Surface Water Control Run-on/off Control System Surface Water Control Pre Adequate Maintenance of I Leachate Leaks or Evidence Survey Controls Leachate Collection System Cause Discharge/Leachate Erosion or Other Cover De Overfill/off Lined Area I Report dwater Monitoring Report	Operations Cate Item Description Annual Compliance Inspection by Registered Professional Engine Cate Item Description Operations in Accordance with Permit Documents Adequate All Weather Operational Roads Smallest Practical Area, Unloading Supervised, Single Working F. Operations by Licensed On-site Operator at all Times Waste Spread and Compacted as Unloaded Surface Water Control Run-on/off Control System Present and Adequate Surface Water Control Prevents Off-site Sediment Accumulation Adequate Maintenance of Intermediate/Final Cover Vegetation Leachate Leaks or Evidence of Leachate Seepage Survey Controls Leachate Collection System Cate Item Description Satisfactory Daily/Intermediate/Alternative Cover Cause Discharge/Leachate Discharge Leaving Landfill Erosion or Other Cover Defects Resulting in Exposed Refuse Overfill/off Lined Area Rec Rec Report dwater Monitoring Report Not in Operation	Soo E. Reynolds Rd. Arkadelphia, AR 71923 Ema 10/25/23 Category 1 Item Description Annual Compliance Inspection by Registered Professional Engineer Category 2 Item Description Operations in Accordance with Permit Documents Adequate All Weather Operational Roads Smallest Practical Area, Unloading Supervised, Single Working Face Operations by Licensed On-site Operator at all Times Waste Spread and Compacted as Unloaded Surface Water Control Run-on/off Control System Present and Adequate Surface Water Control Prevents Off-site Sediment Accumulation Adequate Maintenance of Intermediate/Final Cover Vegetation Leachate Leaks or Evidence of Leachate Seepage Survey Controls Leachate Collection System Category 3 Item Description Satisfactory Daily/Intermediate/Alternative Cover Cause Discharge/Leachate Discharge Leaving Landfill Erosion or Other Cover Defects Resulting in Exposed Refuse Overfill/off Lined Area Records IReport Not in Operation Signature	Son E. Reynolds Rd. Arkadelphia, AR 71923 Email Address Entry Time	Category 1 Item Description Annual Compliance Inspection by Registered Professional Engineer Item Description Operations in Accordance with Permit Documents Adequate All Weather Operational Roads Smallest Practical Area, Unloading Supervised, Single Working Face Operations by Licensed On-site Operator at all Times Waste Spread and Compacted as Unloaded Surface Water Control Run-on/off Control System Present and Adequate Surface Water Control Prevents Off-site Sediment Accumulation Adequate Maintenance of Intermediate/Final Cover Vegetation Leachate Leaks or Evidence of Leachate Seepage Survey Controls Leachate Collection System	Son E. Reynolds Rd. Arkadelphia, AR 71923 Email Address Cole.clark@veolia.con	Son E. Reynolds Rd. Arkadelphia, AR 71923 Email Address Cole_clark@veolia.com PDS # Exit Time 1000 Exit Time 1000