



DIVISION OF ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders

GOVERNOR

Shane E. Khoury

SECRETARY

11/29/2023

Ms. Kelley Crouch
Domtar A. W. Corp.
285 Hwy. 71 South
Ashdown, AR 71822-0496

RE: Inspection conducted on November 8, 2023
AFIN 41-00002
Permit Number 0244-S3N-R1

Dear Ms. Crouch:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or matthew.greenwood@arkansas.gov.

Sincerely,

A handwritten signature in black ink, appearing to read "Matthew Greenwood".

Matthew Greenwood
Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

Division of Environmental Quality
Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Domtar A.W. LLC Mill Waste	County	Little River	AFIN	41-00002
Facility Address	Hwy. 71 S. of Ashdown	Phone #	870-898-2711 Ext 6172	Permit #	0244-S3N-R1
Permittee Address	285 hwy. 71 South Ashdown, AR 71822-0496	Email Address	kelley.crouch@domtar.com	PDS #	128416
Date	11/08/23	Entry Time	1000	Exit Time	1130

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	June 2023	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	March 2023	Previous Quarter Waste Received	3,068

Operator Name & Number	Charles D. Schuetz 002943 Charles Allen	Signature of Inspector	
Exit Interview Conducted with	Charles Allen	Method	On-Site
		Date	11/08/23
		Time	1120