

DIVISION OF ENVIRONMENTAL QUALITY Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

11/29/2023

Mr. Blake Small Eco-Vista, LLC 2210 Waste Management Drive Springdale, AR 72762

RE: Inspection conducted on November 27, 2023 AFIN 72-00144 Permit Number 0290-S1-R4

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@adeq.state.ar.us

Sincerely,

Jason Gilkey Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

		Division of Env		-	llity				
		Office of L	and Re	sources					
		Class 1 Landfi	ill Inspe	ection Fo	rm				
Site Name	Eco-Vista Class 1 Landfill	County			Washington	AFIN	72-00144		
Facility Address	2210 Waste Management D	rive, Springdale, AR 72762	Phone #		870-510-0174	Permit #	0290-S1-R4		
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762		Email Address		bsmall@wm.com	PDS #	128418		
	5				dtenniso@wm.com				
Date	11/27/2023		Entry 7	ſime	1227	Exit Time	1520		
		Operation	nal Star	ndards					
			tegory 1						
Regulation	Item	Description		Comments					
417	Access Requirements								
411(j)	Adequate Provision for Backup	o Equipment							
423(b)	Annual Compliance Inspection by Registered Engineer								
		Ca	tegory 2						
Regulation	Item	Description			Commer	nts			
411(a)	Operations in Accordance with Permit Documents								
411(c)	Smallest Practical Area, Unloa	ding Supervised, Single Working	Face						
411(b)	Operations by Licensed On-site	e Personnel at All Times							
411(g)	Litter Control Provisions Main	tained							
427	Surface Water Controls								
411(h)(1)	Contouring Prevents Surface V	Vater Flowing Into or Through W	Vaste						
418(a)(b)	Run-on/off Control System Pre	esent and Adequate							
411(h)(2)	Surface Water Control Preven	ts Off-site Sediment Accumulatio	n						
411(i)	Adequate Maintenance of Inter	rmediate/Final Cover Vegetation							
415	Gas Monitoring Program								
411(0)	Leachate Leaks or Evidence of Leachate Seepage								
429	Leachate Collection System								
		Ca	tegory 3						
Regulation	Item Description			Comments					
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover								
419(a)(5)	Cause Discharge/Leachate Lea	9							
411(f)(3)	Depositing Waste in Standing								
411(0)	Erosion or Other Cover Defect	s Resulting in Exposed Refuse							
309(c)	Overfill/Off Lined Area								
			Records						
Date of Last Annual Report		3/31/2023		_	terly Methane Monitoring				
Date of Last Groun	dwater Monitoring Report	9/29/2023	Previou	is Quarter	Waste Received	31,972.38 Tons (October 2023)			

Operator Name & Number	Don Tennison 002769	Signature of Inspector			Jacon C. Hilkey		
Exit Interview Conducted with	Don Tennison	Method	On-site	Date	11/27/2023	Time	1515