

DIVISION OF ENVIRONMENTAL QUALITY Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

12/27/2023

Mr. Charles Seaton OMSWD P.O. Box 1669 Harrison, AR 72602

RE: Inspection conducted on December 20, 2023 AFIN 03-00051 Permit Number 0249-S4

Dear Mr. Seaton,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or darrell.norton@adeq.state.ar.us

Sincerely,

Dance Monton

Darrell Norton Solid Waste Inspector

cc: Nicholas Jones P.E., Senior Operations Manager, Office of Land Resources

| | | | Land | Resources | • | | | | |
|--------------------|--|--|---|------------------------|---------------------------------|----------------|---------|--|--|
| | | Class 4 Land | fill In | spection For | n | | | | |
| Site Name | NABORS Landfill -Class 4 | | unty | Baxter | AFIN | 03-00051 | | | |
| Facility Address | Hwy 5 N to CR 16 to site entrance- Three Brothers Pho | | | one # | 870-425-3213 | Permit # | 0249-S4 | | |
| Permittee Address | P.O. Box 1669 | | ail Address | chuckwseaton@gmail.com | PDS # | 128708 | | | |
| | Harrison, AR 72602 | | | | judge@baxtercounty.org | | | | |
| Date | e 12/20/2023 | | | | 1051 | Exit Time | 1200 | | |
| | | Operatio | onal S | Standards | | | | | |
| | | | ategoi | | | | | | |
| Regulation | Item I | Description | | Comments | | | | | |
| 617(a)(b) | Record Keeping Requirements | | | | | | | | |
| 607(j) | Adequate Provisions for Backu | o Equipment | | | | | | | |
| 619 | Annual Compliance Inspection | by Registered Professional Eng | gineer | | | | | | |
| | | | | | | | | | |
| | | С | ategoi | ·y 2 | | | | | |
| Regulation | | Description | Comments | | | | | | |
| 607(a) | Operations in Accordance with | Operations in Accordance with Permit Documents | | | | | | | |
| 613(c) | Adequate All Weather Operation | onal Roads | | | | | | | |
| 607(c)(d) | Smallest Practical Area, Single | Working Face | | | | | | | |
| 607(b) | Operations by Licensed On-site | Personnel at All Times | | | | | | | |
| 607(g) | Litter Control Provisions Main | ained | | | | | | | |
| 622 | Survey Controls | | | | | | | | |
| 623 | Surface Water Controls | | | | | | | | |
| 607(h)(1) | Contouring Prevents Surface W | ater Flowing Into or Through | Waste | | | | | | |
| 607(h)(2) | Surface Water Control Prevent | s Off-site Sediment Accumulat | | | | | | | |
| 607(i)(o) | Adequate Maintenance of Inter | mediate/Final Cover Vegetatio | | | | | | | |
| 607(o) | Leachate Leaks or Evidence of | Leachate Seepage | | | | | | | |
| | | | , | | | | | | |
| Dogulation | It area I | | ategoi | -y 3 | Commonte | | | | |
| Regulation 608 | | Description | | | Comments | | | | |
| 609(a) | Implementation of Hazardous Waste Exclusion PlanSatisfactory Weekly or More Frequent Cover | | | | | | | | |
| 609(b) | Satisfactory Immediate Cover | equent Cover | | | | | | | |
| 615 | Cause Discharge/Leachate Disc | harge Leaving Landfill | | | | | | | |
| 607(o) | Erosion or Other Cover Defects | 8 | | | | | | | |
| 309(c) | Overfill/Off Lined Area | Resarcing in Exposed Relase | | | | | | | |
| 505(0) | | | LCS 9 observed with the pump in the off position and a pump fault read-out. | | | | | | |
| | | | Recor | | | a pump munt fo | | | |
| Date of Last Annua | l Report | 9/16/2013 | | | rly Methane Monitoring 5, | 8/2023 | | | |
| | dwater Monitoring Report | 10/2022 | | evious Quarter W | ing information information ing | | | | |

| Operator Name & Number | n/a | | Signature of Inspector | | | Darrece Monton | | | | | | | |
|-----------------------------------|-----|--|------------------------|-----|------|----------------|------|-----|--|--|--|--|--|
| Exit Interview Conducted with | n/a | | Method | n/a | Date | n/a | Time | n/a | | | | | |