

Sarah Huckabee Sanders GOVERNOR Shane E. Khoury SECRETARY

2/7/2024

Mr. Robert Hendrix Craighead SWDA P.O. Box 16777 Jonesboro, AR 72403

RE: Inspection conducted on February 6, 2024

AFIN 16-00199

Permit Number 0254-S1-R4

Dear Mr. Hendrix,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-2097 or Tobin.Baker@adeq.state.ar.us

Sincerely,

Tobin Baker

Jobn Boker

Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

16Division of Environmental Quality Office of Land Resources Class 1 Landfill Inspection Form

			Class I Landi	<u>m mspe</u>	cuon fori	<u>[]</u>				
Site Name Craighead County SWDA C			Class 1 Count		nty Craighead				AFIN	16-00199
Facility Address	,			Phone #		870-972-63	53		Permit #	0254-S1-R4
Permittee Address	P.O. Box 16777, Jo	nesboro .	AR 72403	Email A	ddress	rhendrix@c	cswda.c	om	PDS#	129120
Date 2/6/2024				Entry Time 1005					Exit Time	1230
			Operatio	nal Stan	dards					
			Ca	tegory 1						
Regulation	Item Description Comments									
417	Access Requirements									
411(j)	Adequate Provision f	or Backup	Equipment							
423(b)	Annual Compliance l	nspection	by Registered Engineer							
·	•		Ca	tegory 2						
Regulation			Description				Con	ments		
411(a)	Operations in Accord									
411(c)			ding Supervised, Single Working	g Face						
411(b)	Operations by Licens	ed On-site	e Personnel at All Times							
411(g)	Litter Control Provisions Maintained									
427	Surface Water Controls									
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste									
418(a)(b)	Run-on/off Control System Present and Adequate									
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation									
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation									
415	Gas Monitoring Program									
411(o)	Leachate Leaks or Evidence of Leachate Seepage									
429	429 Leachate Collection System									
_	<u> </u>		Ca	tegory 3						
Regulation			Description				Con	ıments		
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover									
419(a)(5)		Cause Discharge/Leachate Leaving Landfill								
411(f)(3)	Depositing Waste in S	Depositing Waste in Standing Water Prohibited								
411(o)	Erosion or Other Cov	Erosion or Other Cover Defects Resulting in Exposed Refuse								
309(c)	Overfill/Off Lined A	rea								
	•			Records						
				Date of	Last Quartei	rly Methane	Monito	11118	12/20/2023	
Date of Last Groun	dwater Monitoring	Report	2/8/2023	Previou	s Quarter W	aste Receive	d	(Class 1- 23,489.27	Class 4-10,187.85
Operator Name & Number Robe			Hendrix 00336		gnature of Inspector			Jobin Broken		
Exit Interview Cond	Exit Interview Conducted with Rober			Method	ethod On-site I			2/6/202	4	Time 1220
					+					· · · · · · · · · · · · · · · · · · ·

Division of Environmental Quality Official Photograph Sheet

Location	Craighead County SWD			SWDA Class	1	Permit	0254-S1-R4	AFIN	16-00199
Photographer Tobin Baker, Inspector					TB	Witness	N/A		
Photo #	1	Of	1		•	Date	2/6/2024	Time	1100
Description	ı	Craigh	ead Co	unty SWDA C	Class 1	•	•	•	•