



DIVISION OF
ENVIRONMENTAL QUALITY

129190

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

2/13/2024

The Honorable Woody Wheelless
Crittenden County Judge
100 Court Square
Marion, AR 72364

RE: Inspection conducted on February 7, 2024
AFIN 18-00094
Permit Number 0245-S1-R2

Dear Judge Wheelless,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or Tobin.Baker@adeq.state.ar.us.

Sincerely,

A handwritten signature in dark ink that reads "Tobin Baker".

Tobin Baker
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

**Division of Environmental Quality
Office of Land Resources
Class 1 Landfill Inspection Form**

Site Name	Crittenden County Class 1	County	Crittenden	AFIN	18-00094
Facility Address	1299 Khun Rd. West Memphis, AR 72301	Phone #	LF: 870-732-4290 Off: 870-732-6580	Permit #	0245-S1-R2
Permittee Address	100 Court Street Marion, AR 72364	Email Address	judgewheeless@crittco.com	PDS #	129190
Date	2/7/2024	Entry Time	1240	Exit Time	1404

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2

	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
X	411(o)	Leachate Leaks or Evidence of Leachate Seepage	Leachate leaks observed below the working face in Cell 5. (Refer to Photos #1- #3.)
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
X	411(f)(3)	Depositing Waste in Standing Water Prohibited	Leachate observed discharging from Cell 5 below the working face to an unlined area beside the cell. (Refer to Photos #1 - #3.)
	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/31/2023	Date of Last Quarterly Methane Monitoring	1/31/2024
Date of Last Groundwater Monitoring Report	9/5/2023	Previous Quarter Waste Received	22,984.22

Operator Name & Number	Ed Jackson- 001217	Signature of Inspector			Tobin Boller		
Exit Interview Conducted with	Dallis Bugg	Method	Phone	Date	2/7/2024	Time	1350

Division of Environmental Quality **Official Photograph Sheet**

Location	Crittenden County Class 1 Landfill			Permit	0245-S1-R2	AFIN	18-00094
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	1	Of	3	Date	2/7/2024	Time	1316
Description	Leachate leaks observed below the working face in Cell 5.						



Location	Crittenden County Class 1 Landfill			Permit	0245-S1-R2	AFIN	18-00094
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	2	Of	3	Date	2/7/2024	Time	1316
Description	Leachate and solid waste observed discharging from Cell 5 below the working face to an unlined area beside the cell.						



**Division of Environmental Quality
Official Photograph Sheet**

Location	Crittenden County Class 1 Landfill				Permit	0245-S1-R2	AFIN	18-00094
Photographer	Tobin Baker, Inspector				Witness	N/A		
Photo #	3	Of	3		Date	2/7/2024	Time	1317
Description	Leachate and solid waste observed discharging from Cell 5 below the working face to an unlined area beside the cell.							
								