



DIVISION OF
ENVIRONMENTAL QUALITY

129475

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

3/7/2024

Brandon Bradberry
Plant Manager
Entergy Independence SES
555 Point Ferry Road
Newark, AR 72562

RE: Inspection conducted on February 27 2024
AFIN 32-00042
Permit Number 0200-S3N-R2

Dear Mr. Bradberry,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or darrell.norton@adeq.state.ar.us

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Regulated Waste Operations

**Office of Land Resources
Regulated Waste Operations
Class 3 Landfill Inspection Form**

Site Name	Entergy- Independence Plant	County	Independence	AFIN	32-00042
Facility Address	555 Point Ferry , Newark, AR 72562	Phone #	870-799-8761 Entergy 870-799-3565	Permit #	0200-S3N-R2
Permittee Address	555 Point Ferry , Newark, AR 72562	Email Address	Awilsol@entergy.com	PDS #	129475
Date	2/27/2024	Entry Time	0921	Exit Time	1045

Operational Standards

Category 1

	Regulation	Item Description	Comments
	522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2


	Regulation	Item Description	Comments
	510(a)	Operations in Accordance with Permit Documents	
	516(c)	Adequate All Weather Operational Roads	
	510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	510(b)	Operations by Licensed On-site Operator at all Times	
	510(d)	Waste Spread and Compacted as Unloaded	
	518	Surface Water Control	
	517(a)(b)	Run-on/off Control System Present and Adequate	
	510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	510(n)	Leachate Leaks or Evidence of Leachate Seepage	
	526	Survey Controls	
	529	Leachate Collection System	

Category 3


	Regulation	Item Description	Comments
	512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
	518	Cause Discharge/Leachate Discharge Leaving Landfill	
	510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	6/19/2023	Date of Last Quarterly Methane Monitoring	n/a
Date of Last Groundwater Monitoring Report	Nov 6-9, 2023	Previous Quarter Waste Received	27328.68 tons

Operator Name & Number	Patrick Davenport 004564 (B) Brian Malone 001499 (C)	Signature of Inspector	
Exit Interview Conducted with	Patrick Davenport	Method	In person
		Date	2/27/2024
		Time	1035

Division of Environmental Quality Official Photograph Sheet

Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton , Inspector		<i>DN</i>	Witness	Patrick Davenport, facility operator		
Photo #	1	Of	2	Date	2/27/2024	Time	1003
Description	A view of cells 15, 12, 11 and 8, with slope stabilization in progress.						
							
Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DN</i>	Witness	Patrick Davenport, facility operator.		
Photo #	2	Of	2	Date	2/27/2024	Time	1009
Description	A view of cell 15, looking east toward the active working face.						
