



**DIVISION OF  
ENVIRONMENTAL  
QUALITY**

Sarah Huckabee Sanders  
GOVERNOR

Shane E. Khoury  
SECRETARY

June 13, 2024

Brenda J. Weldon, Mayor  
City of Malvern  
119 W. 3rd St.  
Malvern, AR 72104  
mayor@malvernar.gov

RE: City of Malvern Inspection – PDS# 130728  
AFIN: 30-00040 Permit No.: AR0034126

Dear Mayor Weldon:


On April 23, 2024, I performed an inspection of Manhole 0086 located at the intersection of Kelly St. and Morzett St. in Malvern, Arkansas. The inspection was conducted in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

No violations were noted at the time of the inspection. Please refer to the inspection report for any comments. If I can be of any assistance, please contact me at [Jason.Bolenbaugh@arkansas.gov](mailto:Jason.Bolenbaugh@arkansas.gov) or (501) 682-0659.


Sincerely,

A handwritten signature in black ink, appearing to read "Jason Bolenbaugh".

Jason Bolenbaugh  
Compliance Branch Manager, Office of Water Quality

 <b>ENVIRONMENTAL QUALITY</b>		<b>OFFICE OF WATER QUALITY INSPECTION REPORT</b>				
		AFIN: <b>30-00040</b>		PERMIT #: <b>AR0034126</b>		DATE: <b>4/23/2024</b>
		COUNTY: <b>30 Hot Spring</b>		PDS #: <b>130728</b>		MEDIA: <b>WN</b>
		GPS LAT: <b>34.3610</b> LONG: <b>-92.8248</b> LOCATION: <b>General Area</b>				
<b>FACILITY INFORMATION</b>			<b>INSPECTION INFORMATION</b>			
NAME: <b>City of Malvern</b> LOCATION: <b>3672 Grigsby Ford Rd.</b> CITY: <b>Malvern</b>			FACILITY TYPE: <b>1 - Municipal</b> INSPECTOR ID#: <b>83321 S - State</b>			
			FACILITY EVALUATION RATING: <b>3 - Satisfactory</b> INSPECTION TYPE: <b>Sanitary Sewer Overflow</b>			
			DATE(S): <b>4/23/2024</b> ENTRY TIME: <b>09:30</b> EXIT TIME: <b>09:55</b>			
			PERMIT EFFECTIVE DATE: <b>5/1/2021</b> PERMIT EXPIRATION DATE: <b>4/30/2026</b>			
<b>RESPONSIBLE OFFICIAL</b>						
NAME: / TITLE <b>Brenda J. Weldon / Mayor</b> COMPANY: <b>City of Malvern</b> MAILING ADDRESS: <b>119 W. 3<sup>rd</sup> St.</b> CITY, STATE, ZIP: <b>Malvern AR 72104</b> PHONE & EXT: / FAX: <b>501-332-3638 /</b> EMAIL: <b>mayor@malvernar.gov</b>			FAYETTEVILLE SHALE RELATED: <b>N</b> FAYETTEVILLE SHALE VIOLATIONS: <b>N</b>			
CONTACTED DURING INSPECTION: <b>No</b>			<b>INSPECTION PARTICIPANTS</b>			
			NAME/TITLE/PHONE/FAX/EMAIL/ETC.:			
<b>AREA EVALUATIONS</b>						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
**	PERMIT	**	FLOW MEASUREMENT	**	STORMWATER	
**	RECORDS/REPORTS	**	LABORATORY	**	FACILITY SITE REVIEW	
**	OPERATION & MAINTENANCE	**	EFFLUENT/RECEIVING WATER	**	SELF-MONITORING PROGRAM	
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	**	PRETREATMENT	
**	OTHER:					

<b>SUMMARY OF FINDINGS</b>
<p>At the time of the inspection the manhole (MH0086) was not overflowing as seen previously during an inspection on April 10, 2024.</p> <p>Consent Administrative Order (CAO) LIS# 24-045 was executed and is addressing SSO's within the City of Malvern. A copy of the CAO can be viewed using the following link:  <a href="https://www.adeq.state.ar.us/downloads/WebDatabases/PermitsOnline/NPDES/EnforcementReports/AR0034126_Executed%20CAO%20LIS%2024-045_20240301.pdf">https://www.adeq.state.ar.us/downloads/WebDatabases/PermitsOnline/NPDES/EnforcementReports/AR0034126_Executed%20CAO%20LIS%2024-045_20240301.pdf</a></p>
<b>GENERAL COMMENTS</b>
<p>This inspection of the manhole (MH0086) was conducted while conducting a site visit of the Anthony Timberlands Inc. facility and surrounding areas.</p>

INSPECTOR'S SIGNATURE: 	←Click text to left to add signature	-Inspector Name	DATE:
SUPERVISOR'S SIGNATURE:		Jason Bolenbaugh	DATE: <b>6/13/2024</b>

**Office of Water Quality Photographic Evidence Sheet**

Location:	<b>City of Malvern</b>		
Photographer:	<b>Jason Bolenbaugh</b>	Date:	<b>4/23/2024</b>
Time:	<b>09:31</b>	Photo #:	<b>1</b>
Witness:			
Description:	<b>DSCN7085: MH0086 operating properly.</b>		



Photographer:	<b>Jason Bolenbaugh</b>	Date:	<b>4/23/2024</b>
Time:	<b>09:32</b>	Photo #:	<b>2</b>
Witness:			
Description:	<b>DSCN7086: Discharge pipe from MH0086 entering weir box.</b>		





**Office of Water Quality Photographic Evidence Sheet**

Location:	<b>City of Malvern</b>		
Photographer:	<b>Jason Bolenbaugh</b>	Date:	<b>4/23/2024</b>
Time:	<b>09:49</b>	Photo #:	<b>3</b>
Witness:			
Description:	<b>DSCN7103: Culvert that discharge overflows into the concrete ditch.</b>		



Photographer:	<b>Jason Bolenbaugh</b>	Date:	<b>4/23/2024</b>
Time:	<b>09:49</b>	Photo #:	<b>4</b>
Witness:			
Description:	<b>DSCN7104: Concrete ditch downstream of the culvert in Photo 3.</b>		

