



DIVISION OF
ENVIRONMENTAL QUALITY

131020

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

7/9/2024

The Honorable Woody Wheelless
Crittenden County Judge
100 Court Square
Marion, AR 72364

RE: Inspection conducted on June 24, 2024
AFIN 18-00094
Permit Number 0245-S1-R2

Dear Judge Wheelless,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. The inspection identified conditions at your facility which the DEQ alleges are violations. A copy of the inspection report is attached.

You should immediately initiate actions to correct the alleged violations cited. A written response of the corrective actions taken, or to be taken, must be submitted within thirty (30) calendar days from the date on this letter to the attention of Tobin Baker. The response may include, but is not limited to, photographs, copies of disposal receipts, records, or analytical results, as applicable. If you have any questions regarding the alleged violations, please do not hesitate to contact me at (501) 837-2097 or Tobin.Baker@adeq.state.ar.us.

Sincerely,

A handwritten signature in dark ink that reads 'Tobin Baker'.

Tobin Baker
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

**Division of Environmental Quality
Office of Land Resources
Class 1 Landfill Inspection Form**

Site Name	Crittenden County Class 1	County	Crittenden	AFIN	18-00094
Facility Address	1299 Khun Rd. West Memphis, AR 72301	Phone #	LF: 870-732-4290 Off: 870-732-6580	Permit #	0245-S1-R2
Permittee Address	100 Court Street Marion, AR 72364	Email Address	judgewheeless@crittco.com	PDS #	131020
Date	6/24/2024	Entry Time	0915	Exit Time	1000

Operational Standards

Category 1

	Regulation	Item Description	Comments
	417	Access Requirements	
	411(j)	Adequate Provision for Backup Equipment	
	423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2

	Regulation	Item Description	Comments
	411(a)	Operations in Accordance with Permit Documents	
	411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
	411(b)	Operations by Licensed On-site Personnel at All Times	
	411(g)	Litter Control Provisions Maintained	
	427	Surface Water Controls	
	411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	418(a)(b)	Run-on/off Control System Present and Adequate	
	411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
	415	Gas Monitoring Program	
	411(o)	Leachate Leaks or Evidence of Leachate Seepage	
	429	Leachate Collection System	

Category 3

	Regulation	Item Description	Comments
	413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
	419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
	411(f)(3)	Depositing Waste in Standing Water Prohibited	
	411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
X	309(c)	Overfill/Off Lined Area	Overfill conditions exist near the top of Cell 2 and Cell 3 as specified in Document #85464.

Records

Date of Last Annual Report	3/31/2024	Date of Last Quarterly Methane Monitoring	5/7/2024
Date of Last Groundwater Monitoring Report	2/12/2024	Previous Quarter Waste Received	24,564.40

Operator Name & Number	Ed Jackson- 001217	Signature of Inspector			Tobin Baker		
Exit Interview Conducted with	Josh Kirkpatrick	Method	On-site	Date	6/24/2024	Time	0955