

**From:** Watkins, Glenn E.  
**Sent:** Monday, August 26, 2024 8:36 AM  
**To:** christopher.ayers@domtar.com  
**Cc:** Ryan Hayden (adpce.ad); Christopher Krou (adpce.ad); Kimberly Davenport (adpce.ad); Matthew Greenwood (adpce.ad)  
**Subject:** Domtar A.W. LLC Paper Sludge Class 3 - Q3 Inspection Report - No Violations  
**Attachments:** 131693-insp.pdf

Attached: 08/13/2024 - Domtar A.W. LLC Paper Sludge Class 3 - Q3 Inspection Report - No Violations

Glenn Watkins | Solid Waste Inspector Supervisor  
**Division of Environmental Quality | Office of Land Resources**  
5301 Northshore Drive | North Little Rock, AR 72118  
t: 501.682.0912 | c:501.607.7215 | e: [glenn.e.watkins@arkansas.gov](mailto:glenn.e.watkins@arkansas.gov)



**ARKANSAS**  
ENERGY & ENVIRONMENT



## DIVISION OF ENVIRONMENTAL QUALITY

Sarah Huckabee Sanders

GOVERNOR

Shane E. Khouri

SECRETARY

08/26/2024

Mr. Brandon Ayers  
Domtar A. W. Corp.  
285 Hwy. 71 South  
Ashdown, AR 71822-0496

**RE: Inspection conducted on August 13, 2024  
AFIN 41-00002  
Permit Number 0211-S3N-R2**

Dear Mr. Ayers:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or [matthew.greenwood@arkansas.gov](mailto:matthew.greenwood@arkansas.gov).

Sincerely,

A handwritten signature in black ink, appearing to read 'Matthew Greenwood'.

Matthew Greenwood  
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Regulated Waste Operations

**Division of Environmental Quality**  
**Office of Land Resources**  
**Class 3 Landfill Inspection Form**

|                          |  |                      |  |                  |             |
|--------------------------|--|----------------------|--|------------------|-------------|
| <b>Site Name</b>         | Domtar A.W. LLC Paper Sludge             | <b>County</b>        | Little River   | <b>AFIN</b>      | 41-00002    |
| <b>Facility Address</b>  | Hwy. 71 S. of Ashdown                    | <b>Phone #</b>       | 870-898-2711 Ext 6172  | <b>Permit #</b>  | 0211-S3N-R2 |
| <b>Permittee Address</b> | 285 hwy. 71 South Ashdown, AR 71822-0496 | <b>Email Address</b> | <a href="mailto:Christopher.Ayers@domtar.com">Christopher.Ayers@domtar.com</a> | <b>PDS #</b>     | 131693      |
| <b>Date</b>              | 08/13/24                                 | <b>Entry Time</b>    | 1000   | <b>Exit Time</b> | 1120        |

**Operational Standards**

**Category 1**

| <b>Regulation</b> | <b>Item Description</b>  | <b>Comments</b> |
|-------------------|--|-----------------|
| 522(a)            | Annual Compliance Inspection by Registered Professional Engineer |                 |

**Category 2**

| <b>Regulation</b> | <b>Item Description</b>  | <b>Comments</b> |
|-------------------|--|-----------------|
| 510(a)            | Operations in Accordance with Permit Documents                     |                 |
| 516(c)            | Adequate All Weather Operational Roads                             |                 |
| 510(c)            | Smallest Practical Area, Unloading Supervised, Single Working Face |                 |
| 510(b)            | Operations by Licensed On-site Operator at all Times               |                 |
| 510(d)            | Waste Spread and Compacted as Unloaded                             |                 |
| 518               | Surface Water Control  |                 |
| 517(a)(b)         | Run-on/off Control System Present and Adequate                     |                 |
| 510(h)(2)         | Surface Water Control Prevents Off-site Sediment Accumulation      |                 |
| 510(h)(i)         | Adequate Maintenance of Intermediate/Final Cover Vegetation        |                 |
| 510(n)            | Leachate Leaks or Evidence of Leachate Seepage                     |                 |
| 526               | Survey Controls  |                 |
| 529               | Leachate Collection System   |                 |

**Category 3**

| <b>Regulation</b> | <b>Item Description</b>                                    | <b>Comments</b> |
|-------------------|--|-----------------|
| 512(a)(b)(c)      | Satisfactory Daily/Intermediate/Alternative Cover          |                 |
| 518               | Cause Discharge/Leachate Discharge Leaving Landfill        |                 |
| 510(n)            | Erosion or Other Cover Defects Resulting in Exposed Refuse |                 |
| 309(c)            | Overflow/off Lined Area                                    |                 |

**Records**

|   |            |  |     |
|---|------------|--|-----|
| <b>Date of Last Annual Report</b>                 | June 2024  | <b>Date of Last Quarterly Methane Monitoring</b> | N/A |
| <b>Date of Last Groundwater Monitoring Report</b> | March 2024 | <b>Previous Quarter Waste Received</b>           | 0   |

|                                      |  |                               |   |             |          |             |      |
|--------------------------------------|--|-------------------------------|---|-------------|----------|-------------|------|
| <b>Operator Name &amp; Number</b>    | Charles D. Schuetz 002943<br>Charles Allen | <b>Signature of Inspector</b> |  |             |          |             |      |
| <b>Exit Interview Conducted with</b> | Charles Allen                              | <b>Method</b>                 | On-Site   | <b>Date</b> | 08/13/24 | <b>Time</b> | 1115 |