

**From:** Kimberly Davenport (adpce.ad)  
**Sent:** Tuesday, August 27, 2024 1:51 PM  
**To:** bsmall@wm.com; dtenniso@wm.com  
**Cc:** Jason Gilkey (adpce.ad); Watkins, Glenn E.; Christopher Krou (adpce.ad); Ryan Hayden (adpce.ad)  
**Subject:** Eco Visa Class 1 - Q3 Inspection report - No violations  
**Attachments:** 131719-insp.pdf

Attached:8/14/2024 - Eco Visa Class 1 - Q3 Inspection report - No violations

**Kim Davenport** | Solid Waste Inspector Supervisor  
**Division of Environmental Quality | Office of Land Resources**  
**Regulated Waste Program**  
5301 Northshore Drive | North Little Rock, AR 72118  
t: 501.682.0586 | c: 501.837.6911 | e: [Kimberly.Davenport@arkansas.gov](mailto:Kimberly.Davenport@arkansas.gov)



**ARKANSAS**  
ENERGY & ENVIRONMENT



DIVISION OF  
ENVIRONMENTAL QUALITY

131719

Sarah Huckabee Sanders  
GOVERNOR

Shane E. Khoury  
SECRETARY

8/27/2024

Mr. Blake Small  
Eco-Vista, LLC  
2210 Waste Management Drive  
Springdale, AR 72762

**RE: Inspection conducted on August 14, 2024**  
**AFIN 72-00144**  
**Permit Number 0290-S1-R4**

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or [jason.gilkey@arkansas.gov](mailto:jason.gilkey@arkansas.gov).

Sincerely,

A handwritten signature in black ink that reads "Jason C. Gilkey". The signature is written in a cursive style with a large, sweeping 'J' and 'G'.

Jason Gilkey  
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

**1Division of Environmental Quality  
Office of Land Resources  
Class 1 Landfill Inspection Form**

<b>Site Name</b>	Eco-Vista Class 1 Landfill	<b>County</b>	Washington	<b>AFIN</b>	72-00144
<b>Facility Address</b>	2210 Waste Management Drive, Springdale, AR 72762	<b>Phone #</b>	870-510-0174	<b>Permit #</b>	0290-S1-R4
<b>Permittee Address</b>	2210 Waste Management Drive, Springdale, AR 72762	<b>Email Address</b>	<a href="mailto:bsmall@wm.com">bsmall@wm.com</a> <a href="mailto:dtenniso@wm.com">dtenniso@wm.com</a>	<b>PDS #</b>	131719
<b>Date</b>	8/14/2024	<b>Entry Time</b>	1120	<b>Exit Time</b>	1512

**Operational Standards**

**Category 1**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
417	Access Requirements	
411(j)	Adequate Provision for Backup Equipment	
423(b)	Annual Compliance Inspection by Registered Engineer	

**Category 2**


<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
411(a)	Operations in Accordance with Permit Documents	
411(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
411(b)	Operations by Licensed On-site Personnel at All Times	
411(g)	Litter Control Provisions Maintained	
427	Surface Water Controls	
411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
418(a)(b)	Run-on/off Control System Present and Adequate	
411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
411(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
415	Gas Monitoring Program	
411(o)	Leachate Leaks or Evidence of Leachate Seepage	
429	Leachate Collection System	

**Category 3**

<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
413(a)(b)(c)	Satisfactory Daily/Alternate/Intermediate Cover	
419(a)(5)	Cause Discharge/Leachate Leaving Landfill	
411(f)(3)	Depositing Waste in Standing Water Prohibited	
411(o)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/Off Lined Area	

**Records**

<b>Date of Last Annual Report</b>	3/31/2024	<b>Date of Last Quarterly Methane Monitoring</b>	6/23/2024
<b>Date of Last Groundwater Monitoring Report</b>	6/13/2024	<b>Previous Quarter Waste Received</b>	32,050.52 Tons

<b>Operator Name &amp; Number</b>	Don Tennison 002769	<b>Signature of Inspector</b>					
<b>Exit Interview Conducted with</b>	Don Tennison – Facility Manager	<b>Method</b>	On-site	<b>Date</b>	8/14/2024	<b>Time</b>	1515