



DIVISION OF
ENVIRONMENTAL QUALITY

133031

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

2/18/2025

Brandon Bradberry
Plant Manager
Entergy Independence SES
555 Point Ferry Road
Newark, AR 72562

RE: Inspection conducted on February 3, 2025
AFIN 32-00042
Permit Number 0200-S3N-R2

Dear Mr. Bradberry,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or darrell.norton@arkansas.gov.

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Regulated Waste Operations

**Division of Environmental Quality
Office of Land Resources
Class 3 Landfill Inspection Form**

Site Name	Entergy- Independence Plant	County	Independence	AFIN	32-00042
Facility Address	555 Point Ferry, Newark, AR 72562	Phone #	870-799-8761 Entergy 870-799-3565	Permit #	0200-S3N-R2
Permittee Address	555 Point Ferry, Newark, AR 72562	Email Address	Awilso1@entergy.com	PDS #	133031
Date	2/3/2025	Entry Time	0955	Exit Time	1107

Operational Standards

Category 1

Regulation	Item Description	Comments
522(a)	Annual Compliance Inspection by Registered Professional Engineer	

Category 2

Regulation	Item Description	Comments
510(a)	Operations in Accordance with Permit Documents	
516(c)	Adequate All Weather Operational Roads	
510(c)	Smallest Practical Area, Unloading Supervised, Single Working Face	
510(b)	Operations by Licensed On-site Operator at all Times	
510(d)	Waste Spread and Compacted as Unloaded	
518	Surface Water Control	
517(a)(b)	Run-on/off Control System Present and Adequate	
510(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
510(h)(i)	Adequate Maintenance of Intermediate/Final Cover Vegetation	
510(n)	Leachate Leaks or Evidence of Leachate Seepage	
526	Survey Controls	
529	Leachate Collection System	Both pumps servicing the leachate collection system for Cell 15 observed running at the time of the inspection. The LCS panel for the South pump observed with an active red strobe indicating a high leachate level.

Category 3

Regulation	Item Description	Comments
512(a)(b)(c)	Satisfactory Daily/Intermediate/Alternative Cover	
518	Cause Discharge/Leachate Discharge Leaving Landfill	
510(n)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
309(c)	Overfill/off Lined Area	

Records

Date of Last Annual Report	6/27/2024	Date of Last Quarterly Methane Monitoring	n/a
Date of Last Groundwater Monitoring Report	June 10-13, 2024	Previous Quarter Waste Received	17877.84 tons

Operator Name & Number	Patrick Davenport 004564 (C) Andy Wilson 001442 (Expired C)	Signature of Inspector			<i>Daniel Norton</i>
Exit Interview Conducted with	Andy Wilson (Entergy)	Method	In person	Date	2/3/2025
				Time	1057