



DIVISION OF
ENVIRONMENTAL QUALITY

133274

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

4/4/2025

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Inspection conducted on February 27, 2025
AFIN 72-00144
Permit Number 0290-S1-R4

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60-101 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@arkansas.gov.

Sincerely,

A handwritten signature in black ink, reading 'Jason C. Gilkey'.

Jason Gilkey
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

ARKANSAS DEPARTMENT OF ENERGY AND ENVIRONMENT
ee.arkansas.gov | 5301 Northshore Drive, North Little Rock, AR 72118 |
501.682.0744

02.11.2025

Division of Environmental Quality - Office of Land Resources
Class 1 Landfill Inspection Form

Site Name	Eco-Vista Class 1 Landfill	County	Washington	AFIN	72-00144
Facility Address	2210 Waste Management Drive, Springdale, AR 72762	Phone #	870-510-0174	Permit #	0290-S1-R4
Permittee Address	2210 Waste Management Drive, Springdale, AR 72762	Email Address	bsmall@wm.com dtenniso@wm.com	PDS #	133274
Date	2/27/2025	Entry Time	1110	Exit Time	1435

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-417	Access Requirements	
	8 CAR § 60-411(j)	Adequate Provision for Backup Equipment	
	8 CAR § 60-423(b)	Annual Compliance Inspection by Registered Engineer	

Category 2


	Citation	Description	Comments
	8 CAR § 60-411(a)	Operations in Conformance with Permit Documents	
	8 CAR § 60-411(c)	(Working Face)	
	8 CAR § 60-411(b)	Operations by Licensed On-site Operators at All Times	
	8 CAR § 60-411(g)	Litter Control	
	8 CAR § 60-427	Surface Water Controls	
	8 CAR § 60-411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	8 CAR § 60-418	Run-On/Run-Off Control System Present and Adequate	
	8 CAR § 60-411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-411(i)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-415	Gas Monitoring Program	
	8 CAR § 60-411(o)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	8 CAR § 60-429	Leachate Collection System	

Category 3

	Citation	Description	Comments
	8 CAR § 60-413	Satisfactory Daily/Alternate/Intermediate Cover	
	8 CAR § 60-419(a)(5)	Allow Leachate not permitted under NPDES to Leave Landfill	
	8 CAR § 60-413(f)(3)	Depositing Waste in Standing Water is Prohibited	
	8 CAR § 60-411(o)(1)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	8 CAR § 60-309(c)	Overfill/Off Lined Area	

Records

Date of Last Annual Report	3/29/2024	Date of Last Quarterly Methane Monitoring	1/31/2025
Date of Last Groundwater Monitoring Report	1/3/2025	Previous Quarter Waste Received	90,062.08 Tons

Operator Name & Number	Don Tennison 002769	Signature of Inspector					
Exit Interview Conducted with	Don Tennison – Facility Manager	Method	On-site	Date	2/27/2025	Time	1430

Division of Environmental Quality

Official Photograph Sheet

Location	Eco-Vista Class 1 Landfill	Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey- Inspector	SG	Witness	NA	
Photo #	1	of	2	Date	2/27/2025
Description	A view of the entrance of the landfill, facing southwest.				



Location	Eco-Vista Class 1 Landfill	Permit	0290-S1-R4	AFIN	72-00144
Photographer	Jason Gilkey- Inspector	SG	Witness	NA	
Photo #	2	of	2	Date	2/27/2025
Description	A view of the working face in operation, facing west.				

