



DIVISION OF
ENVIRONMENTAL QUALITY

133275

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

4/4/2025

Mr. Blake Small
Eco-Vista, LLC
2210 Waste Management Drive
Springdale, AR 72762

RE: Inspection conducted on February 27, 2025
AFIN 72-00144
Permit Number 0290-S4-R2

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60-101 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or jason.gilkey@arkansas.gov.

Sincerely,

A handwritten signature in black ink that reads "Jason C. Gilkey".

Jason Gilkey
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

ARKANSAS DEPARTMENT OF ENERGY AND ENVIRONMENT
ee.arkansas.gov | 5301 Northshore Drive, North Little Rock, AR 72118 |
501.682.0744

02.11.2025

Division of Environmental Quality - Office of Land Resources
Class 4 Landfill Inspection Form

| | | | | | |
|--------------------------|---|----------------------|--|------------------|------------|
| Site Name | Eco-Vista Class 4 Landfill | County | Washington | AFIN | 72-00144 |
| Facility Address | 2210 Waste Management Drive, Springdale, AR 72762 | Phone # | 870-510-0174 | Permit # | 0290-S4-R2 |
| Permittee Address | 2210 Waste Management Drive, Springdale, AR 72762 | Email Address | bsmall@wm.com dtenniso@wm.com | PDS # | 133275 |
| Date | 2/27/2025 | Entry Time | 1110 | Exit Time | 1435 |

Operational Standards

Category 1

| | Citation | Description | Comments |
|--|--------------------------|--|-----------------|
| | 8 CAR § 60-617 | Record Keeping Requirements | |
| | 8 CAR § 60-607(j) | Adequate Provisions for Backup Equipment | |
| | 8 CAR § 60-619 | Annual Engineering Inspection Report | |
| | | | |

Category 2


| | Citation | Description | Comments |
|--|--------------------------------|---|-----------------|
| | 8 CAR § 60-607(a) | Operations in Accordance with Permit Documents | |
| | 8 CAR § 60-613(c) | Access and Operational Roads | |
| | 8 CAR § 60-607(c) | Working Face | |
| | 8 CAR § 60-607(b) | Operations by Licensed On-site Operator at All Times | |
| | 8 CAR § 60-607(g) | Litter Control | |
| | 8 CAR § 60-622 | Survey Controls | |
| | 8 CAR § 60-623 | Surface Water Controls | |
| | 8 CAR § 60-607(h)(1) | Contouring Prevents Surface Water Flowing Into or Through Waste | |
| | 8 CAR § 60-607(h)(2)(A) | Surface Water Control Prevents Off-site Sediment Accumulation | |
| | 8 CAR § 60-607(i) | Final Cover Vegetation and Maintenance | |
| | 8 CAR § 60-607(o)(2) | Leachate Leaks or Evidence of Leachate Seepage | |
| | | | |

Category 3

| | Citation | Description | Comments |
|--|-----------------------------|--|-----------------|
| | 6088 CAR § 60-608 | Implementation of Hazardous Waste Exclusion Plan | |
| | 8 CAR § 60-609(a) | Satisfactory Weekly or More Frequent Cover | |
| | 8 CAR § 60-609(b) | Satisfactory Intermediate Cover | |
| | 8 CAR § 60-615(a)(5) | Allow Leachate Unpermitted by NPDES to Leave the Landfill | |
| | 8 CAR § 60-607(o)(1) | Erosion or Other Cover Defects Resulting in Exposed Refuse | |
| | 8 CAR § 60-309(c) | Overfill / Off Lined Area | |
| | | | |

Records

| | | | |
|---|-----------|--|-----------|
| Date of Last Annual Report | 3/29/2024 | Date of Last Quarterly Methane Monitoring | 1/31/2025 |
| Date of Last Groundwater Monitoring Report | 1/3/2025 | Previous Quarter Waste Received | 24,019.19 |

| | | | | | | | |
|--------------------------------------|--------------------------------|-------------------------------|---------|-------------|--|-------------|------|
| Operator Name & Number | Don Tennison 02769 | Signature of Inspector | | |  | | |
| Exit Interview Conducted with | Don Tennison- Facility Manager | Method | On-site | Date | 2/27/2025 | Time | 1430 |

Division of Environmental Quality Official Photograph Sheet

| | | | | | | | | |
|---------------------|--|-----------|-----|--|----------------|------------|-------------|----------|
| Location | Eco-Vista Class 4 Landfill | | | | Permit | 0290-S4-R2 | AFIN | 72-00144 |
| Photographer | Jason Gilkey - Inspector | | JLG | | Witness | NA | | |
| Photo # | 1 | of | 2 | | Date | 2/27/2025 | Time | 1331 |
| Description | A view of the Class 4 working face in operation, facing north. | | | | | | | |



| | | | | | | | | |
|---------------------|---|-----------|-----|--|----------------|------------|-------------|----------|
| Location | Eco-Vista Class 4 Landfill | | | | Permit | 0290-S4-R2 | AFIN | 72-00144 |
| Photographer | Jason Gilkey - Inspector | | JLG | | Witness | NA | | |
| Photo # | 2 | of | 2 | | Date | 2/27/2025 | Time | 1325 |
| Description | Another view of the working face in operation, facing west. | | | | | | | |

