



**DIVISION OF
ENVIRONMENTAL QUALITY**

133504

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

5/27/2025

Mr. Brandon Ayers
Domtar A. W. Corp.
285 Hwy. 71 South
Ashdown, AR 71822-0496

RE: Inspection conducted on April 24, 2025
AFIN 41-00002
Permit Number 0211-S3N-R2

Dear Mr. Ayers:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60-101 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or matthew.greenwood@arkansas.gov.

Sincerely,

A handwritten signature in black ink, appearing to read 'Matthew Greenwood'.

Matthew Greenwood
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Regulated Waste Operations

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Domtar A.W. LLC Paper Sludge	County	Little River	AFIN	41-00002
Facility Address	Hwy. 71 S. of Ashdown	Phone #	870-898-2711 Ext 6172	Permit #	0211-S3N-R2
Permittee Address	285 Hwy. 71 South Ashdown, AR 71822-0496	Email Address	Christopher.Ayers@domtar.com	PDS #	133504
Date	04/24/25	Entry Time	0915	Exit Time	1020

Operational Standards

Category 1

Citation	Description	Comments
8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2

Citation	Description	Comments
8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
8 CAR § 60-516(c)	Access and Operational Roads	
8 CAR § 60-510(c)	Working Face	
8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
8 CAR § 60-518	Surface Water Control	
8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
8 CAR § 60-526	Survey Controls	
8 CAR § 60-529	Leachate Collection System	

Category 3

Citation	Description	Comments
8 CAR § 60-512()	Satisfactory Daily/Intermediate/Alternative Cover	
8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
8 CAR § 60-309(c)()	Overfill / Off Lined Area	

Records

Date of Last Annual Report	06/24/2024	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Groundwater Monitoring Report	02/18/25	Previous Quarter Waste Received	0

Operator Name & Number	Charles D. Schuetz 002943 Jim York	Signature of Inspector	
Exit Interview Conducted with	Jim York	Method	On-Site
		Date	04/24/25
		Time	1015