



DIVISION OF
ENVIRONMENTAL QUALITY

133511

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

May 27, 2025

Brandon Bradberry
Plant Manager
Entergy Independence SES
555 Point Ferry Road
Newark, AR 72562

RE: Inspection conducted on May 5, 2025
AFIN 32-00042
Permit Number 0200-S3N-R2

Dear Mr. Bradberry,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501)837-6909 or Darrell.norton@arkansas.gov.

Sincerely,

A handwritten signature in cursive script that reads "Darrell Norton".

Darrell Norton
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources
Class 3 Landfill Inspection Form

Site Name	Entergy- Independence Plant	County	Independence	AFIN	32-00042
Facility Address	555 Point Ferry, Newark, AR 72562	Phone #	870-799-8761	Permit #	0200-S3N-R2
Permittee Address	555 Point Ferry, Newark, AR 72562	Email Address	Awilsol@entergy.com	PDS #	133511
Date	5/5/2025	Entry Time	1020	Exit Time	1125

Operational Standards

Category 1

Citation	Description	Comments
8 CAR § 60-522	Annual Engineering Inspection Report	

Category 2


Citation	Description	Comments
8 CAR § 60-510(a)	Operations in Accordance with Permit Documents	
8 CAR § 60-516(c)	Access and Operational Roads	
8 CAR § 60-510(c)	Working Face	
8 CAR § 60-510(b)	Operations by Licensed On-site Operator at all Times	
8 CAR § 60-510(d)	Waste Spread and Compacted as Unloaded	
8 CAR § 60-518	Surface Water Control	
8 CAR § 60-517	Run-On/Run-Off Control System Present and Adequate	
8 CAR § 60-510(h)(2)(A)	Surface Water Control Prevents Off-site Sediment Accumulation	
8 CAR § 60-510(i)	Final Cover Vegetation and Maintenance	
8 CAR § 60-510(n)(2)	Leachate Leaks or Evidence of Leachate Seepage	
8 CAR § 60-526	Survey Controls	
8 CAR § 60-529	Leachate Collection System	

Category 3



Citation	Description	Comments
8 CAR § 60-512	Satisfactory Daily/Intermediate/Alternative Cover	
8 CAR § 60-518(a)(5)	Allow Leachate unpermitted by NPDES to Leave Landfill	
8 CAR § 60-510(n)(1)	Erosion or Other Cover Defects Resulting in Exposed Waste	
8 CAR § 60-309(c)	Overfill / Off Lined Area	

Records

Date of Last Annual Report	6/27/2024	Date of Last Quarterly Methane Monitoring	n/a
Date of Last Groundwater Monitoring Report	November 4, 2024	Previous Quarter Waste Received	16550.01 tons (see attached)

Operator Name & Number	Patrick Davenport 004564(C)	Signature of Inspector			
Exit Interview Conducted with	Patrick Davenport	Method	In-person	Date	5/5/2025
				Time	1115

Division of Environmental Quality Official Photograph Sheet

Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DN</i>	Witness	n/a		
Photo #	1	Of	4	Date	5/5/2025	Time	1035
Description	New CCR monitoring well installation work observed at the time of the inspection.						
							
Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DN</i>	Witness	n/a		
Photo #	2	Of	4	Date	5/5/2025	Time	1038
Description	Access road to cell 15 and adjacent storm water ditch as observed at the time of the inspection. Sediment accumulation from heavy April rains observed in the storm water ditches.						
							

Division of Environmental Quality Official Photograph Sheet

Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DN</i>	Witness	n/a		
Photo #	3	Of	4	Date	5/5/2025	Time	1046
Description	The working face observed at the time of the inspection.						



Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DN</i>	Witness	n/a		
Photo #	4	Of	4	Date	5/5/2025	Time	1047
Description	Cell 16 construction observed at the time of the inspection.						

