



DIVISION OF  
ENVIRONMENTAL QUALITY

133738

Sarah Huckabee Sanders  
GOVERNOR

Shane E. Khoury  
SECRETARY

7/11/2025

Mr. Blake Small  
Eco-Vista, LLC  
2210 Waste Management Drive  
Springdale, AR 72762

**RE: Inspection conducted on June 10, 2025**  
**AFIN 72-00144**  
**Permit Number 0290-S1-R4**

Dear Mr. Small,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Rule, codified as 8 CAR § 60-101 (Solid Waste Management Rules), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 993-7188 or [jason.gilkey@arkansas.gov](mailto:jason.gilkey@arkansas.gov).

Sincerely,

A handwritten signature in black ink, reading 'Jason C. Gilkey'.

Jason Gilkey  
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

**ARKANSAS DEPARTMENT OF ENERGY AND ENVIRONMENT**  
ee.arkansas.gov | 5301 Northshore Drive, North Little Rock, AR 72118 |  
501.682.0744

**Division of Environmental Quality - Office of Land Resources**  
**Class 1 Landfill Inspection Form**

<b>Site Name</b>	Eco-Vista Class 1 Landfill	<b>County</b>	Washington	<b>AFIN</b>	72-00144
<b>Facility Address</b>	2210 Waste Management Drive, Springdale, AR 72762	<b>Phone #</b>	870-510-0174	<b>Permit #</b>	0290-S1-R4
<b>Permittee Address</b>	2210 Waste Management Drive, Springdale, AR 72762	<b>Email Address</b>	<a href="mailto:bsmall@wm.com">bsmall@wm.com</a> <a href="mailto:dtenniso@wm.com">dtenniso@wm.com</a>	<b>PDS #</b>	133738
<b>Date</b>	6/10/2025	<b>Entry Time</b>	1310	<b>Exit Time</b>	1613

**Operational Standards**

**Category 1**

	<b>Citation</b>	<b>Description</b>	<b>Comments</b>
	8 CAR § 60-417	Access Requirements	
	8 CAR § 60-411(j)	Adequate Provision for Backup Equipment	
	8 CAR § 60-423(b)	Annual Compliance Inspection by Registered Engineer	

**Category 2**


	<b>Citation</b>	<b>Description</b>	<b>Comments</b>
	8 CAR § 60-411(a)	Operations in Conformance with Permit Documents	
	8 CAR § 60-411(c)	(Working Face)	
	8 CAR § 60-411(b)	Operations by Licensed On-site Operators at All Times	
	8 CAR § 60-411(g)	Litter Control	
	8 CAR § 60-427	Surface Water Controls	
	8 CAR § 60-411(h)(1)	Contouring Prevents Surface Water Flowing Into or Through Waste	
	8 CAR § 60-418	Run-On/Run-Off Control System Present and Adequate	
	8 CAR § 60-411(h)(2)	Surface Water Control Prevents Off-site Sediment Accumulation	
	8 CAR § 60-411(i)	Final Cover Vegetation and Maintenance	
	8 CAR § 60-415	Gas Monitoring Program	
	8 CAR § 60-411(o)(2)	Leachate Leaks or Evidence of Leachate Seepage	
	8 CAR § 60-429	Leachate Collection System	

**Category 3**

	<b>Citation</b>	<b>Description</b>	<b>Comments</b>
	8 CAR § 60-413	Satisfactory Daily/Alternate/Intermediate Cover	
	8 CAR § 60-419(a)(5)	Allow Leachate not permitted under NPDES to Leave Landfill	
	8 CAR § 60-413(f)(3)	Depositing Waste in Standing Water is Prohibited	
	8 CAR § 60-411(o)(1)	Erosion or Other Cover Defects Resulting in Exposed Refuse	
	8 CAR § 60-309(c)	Overfill/Off Lined Area	

**Records**

<b>Date of Last Annual Report</b>	3/29/2024	<b>Date of Last Quarterly Methane Monitoring</b>	5/5/2025
<b>Date of Last Groundwater Monitoring Report</b>	5/22/2025	<b>Previous Quarter Waste Received</b>	30,459.67 Tons

<b>Operator Name &amp; Number</b>	Don Tennison 002769	<b>Signature of Inspector</b>	
<b>Exit Interview Conducted with</b>	Don Tennison – Facility Manager	<b>Method</b>	On-site
		<b>Date</b>	6/10/2025
		<b>Time</b>	1605

# Division of Environmental Quality Official Photograph Sheet

<b>Location</b>	Eco-Vista Class 1 Landfill				<b>Permit</b>	0290-S1-R4	<b>AFIN</b>	72-00144
<b>Photographer</b>	Jason Gilkey- Inspector		JLG		<b>Witness</b>	NA		
<b>Photo #</b>	1	<b>of</b>	2		<b>Date</b>	6/10/2025	<b>Time</b>	1310
<b>Description</b>	A view of the entrance of the landfill, facing southwest.							



<b>Location</b>	Eco-Vista Class 1 Landfill				<b>Permit</b>	0290-S1-R4	<b>AFIN</b>	72-00144
<b>Photographer</b>	Jason Gilkey- Inspector		JLG		<b>Witness</b>	NA		
<b>Photo #</b>	2	<b>of</b>	2		<b>Date</b>	6/10/2025	<b>Time</b>	1553
<b>Description</b>	A view of the working face in operation, facing west.							

