



DIVISION OF
ENVIRONMENTAL QUALITY

134370

Sarah Huckabee Sanders
GOVERNOR

Shane E. Khoury
SECRETARY

Via Email: dford@pmico.com

2/17/2026

Mr. Bryan Moery
Eaton - Morey Environmental Services, Inc.
PO Box 1025
Wynne, AR 72396

RE: Inspection conducted on February 10, 2026
AFIN 19-00091
Permit Number 0269-S3T-R1

Dear Mr. Moery,

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act of 1971, as amended (Arkansas Code Annotated § 8-6-201 *et seq.*), the Arkansas Pollution Control & Ecology Commission (APC&EC) Rule, codified as 8 CAR § 60 (Solid Waste Management Rules), and the above-referenced permit. The inspection identified conditions the DEQ has determined to be in violation of the applicable requirements. A copy of the inspection report is attached and has been forwarded to the Office of Land Resources' Enforcement Section for further consideration regarding your pending case.

Written responses and documentation for all corrective actions should reference your name, facility name, and date of investigation and must be submitted by email to olrenforcement@arkansas.gov and Tobin.Baker@arkansas.gov, or delivered in person or by mail to the address found at the bottom of this letter. If you have any questions regarding the enforcement process, please contact Gina Porter at (501) 682-0636.

Sincerely,

A handwritten signature in black ink that reads "Tobin Baker".

Tobin Baker
Solid Waste Inspector

cc: Ryan Hayden, Senior Compliance Manager, Office of Land Resources

Division of Environmental Quality - Office of Land Resources

Closed Landfill Inspection Form

Site Name	EMS Inc. 3T Monofill	County	Cross	AFIN	19-00091
Facility Address	74 CR 451, Parkin, AR 72373	Phone #	870-318-4422	Permit #	0269-S3T-R1
Permittee Address	PO Box 1025, Wynne, AR 72396	Email Address	dford@pmico.com	PDS #	134370
Date	2/10/2026	Entry Time	1310	Exit Time	1415

Classification		Class 1	<input checked="" type="checkbox"/>	Class 3		Class 4	<input checked="" type="checkbox"/>	Closed
-----------------------	--	----------------	-------------------------------------	----------------	--	----------------	-------------------------------------	---------------

Operational Standards

Category 1

	Citation	Description	Comments
	8 CAR § 60-1302(b)(2)(A)(iii)	Ditches Maintained	
	8 CAR § 60-1302(b)(2)(A)(i)	Settling on Completed Areas	

Category 2


	Citation	Description	Comments
X	8 CAR § 60-522(b)	Annual Engineering Inspection Report	The facility has not submitted an Annual Engineering Inspection Report for the year 2020, 2021, 2022, 2023, and 2024.
	8 CAR § 60-1302(b)(2)(A)(i)	Cover Vegetation Maintained	
	8 CAR § 60-1302(b)(2)(A)(i)	Preventing Run-on/Run-off from Damaging Final Cover	

Category 3

	Citation	Description	Comments
X	8 CAR § 60-1302(b)(2)(A)(iii)	Erosion or Cracking of Soil	Exposed tires observed on the final cover on the north, east, and west sides of the landfill. (Refer to Photos #1- #4). (Refer to Doc. #s 78656, 78843, & 78856.)
	8 CAR § 60-1302(b)(2)(B)(i)	Maintaining & Operating Leachate Collection System	
	8 CAR § 60-1302(b)(2)(C)	Groundwater Monitoring Maintained	
	8 CAR § 60-1302(b)(2)(D)	Maintaining & Operating Gas Monitoring System	

Records

Date of Closure Certification	9/6/2016	Date of Last Leachate Disposal	N/A
Date of Last Annual Report	7/27/2020	Date of Last Quarterly Methane Monitoring	N/A
Date of Last Waste Accepted	N/A	Date of Last Groundwater Monitoring Report	N/A

Operator Name & Number		Signature of Inspector	
-----------------------------------	--	-------------------------------	---

Exit Interview Conducted with	Bryan Moery	Method	Phone	Date	2/11/2026	Time	1318
--------------------------------------	-------------	---------------	-------	-------------	-----------	-------------	------

Division of Environmental Quality Official Photograph Sheet

Location	EMS Inc. Class 3T			Permit	0269-S3T-R1	AFIN	19-00091
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	1	Of	4	Date	2/10/2026	Time	1351
Description	Exposed tire observed on the north side of the landfill.						
							
Location	EMS Inc. Class 3T			Permit	0269-S3T-R1	AFIN	19-00091
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	2	Of	4	Date	2/10/2026	Time	1353
Description	Exposed tire observed on the north side of the landfill.						
							

Division of Environmental Quality Official Photograph Sheet

Location	EMS Inc. Class 3T			Permit	0269-S3T-R1	AFIN	19-00091
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	3	Of	4	Date	2/10/2026	Time	1354
Description	Exposed tire observed on the north side of the landfill.						
							
Location	EMS Inc. Class 3T			Permit	0269-S3T-R1	AFIN	19-00091
Photographer	Tobin Baker, Inspector			Witness	N/A		
Photo #	4	Of	4	Date	2/10/2026	Time	1358
Description	Exposed tire observed on the west side of the landfill.						
							