


# REPORT OF NON COMPLIANCE



NAME OF FACILITY Melbourne, City of  
PERMIT NUMBER AR0020036 001-A  
PERIOD ENDING June 2015

PARAMETER VIOLATED	CLORIDE CONC DAILY MAX						
REPORTED VIOLATIONS	0.10						
PARAMETER VIOLATED	0.1						

WEEK OF Jun 24 15

Please fill out the following information

CAUSE OF VIOLATION the sulfur dioxide was not adjusted properly to compensate for the effluent


DURATION OF VIOLATION just a few hours

CORRECTIVE ACTION adjusted it properly at a higher rate

EXPECTED COMPLIANCE DATE June 25, 2015

SIGNATURE / DATE

# REPORT OF NON COMPLIANCE



NAME OF FACILITY MELBOURNE, CITY OF  
PERMIT NUMBER AR0020036 001-A  
PERIOD ENDING May 2015

PARAMETER VIOLATED	CLORIDE CONC DAILY MAX						
REPORTED VIOLATIONS	0.10						
PARAMETER VIOLATED	0.1						

WEEK OF May 28 15

Please fill out the following information

CAUSE OF VIOLATION had a problem with sulfur dioxide pump  
working properly

DURATION OF VIOLATION a few hours

CORRECTIVE ACTION replaced part that was giving the  
problems

EXPECTED COMPLIANCE DATE May 29, 2015

Ray Dal  
SIGNATURE / DATE