


### Sanitary Sewer Overflow Monthly Report

Facility Name: Mountain View, City of Permit Number: AR0020117 Reporting Period(Month/Year): 5-13

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions				
Cause(s) of SSO		SSO Impact	Action(s) Taken	Ultimate Discharge Loc
CO-Construction	D-Debris	NEAH-No Evidence of Adverse Health or Environmental Impact		CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease	OBHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	BFK-Evidence of Fish Kill	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism		EN-Referred to Engineering	PA-Paved Area
			PN-Public Notification	CB-Contained in Build

Location	Manhole #	Start Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action (s) Taken to Address SSO	Ultimate Discharge Location
ALICE STA PARK ST		5-31-13	6-1-13	3000	R	NEAH	EC	CR


Date JUNE 7-2013

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

MOUNTAIN VIEW  
WATER & SEWER DEPARTMENT  
DRAWER 360  
MOUNTAIN VIEW, AR 72560

LITTLE ROCK AR 722

14 JUN 2013 PM 4 L



ADEQ  
NPDES Enforcement Section  
5301 Northshore Drive  
N. Little Rock, AR 72118-5317

72118531799

