

Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities
 Permit Number: AR0020702
 Reporting Period(Month/Year): March 2020

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summery Report Code Descriptions					Ultimate Discharge Location	
		SSO Impact	Action(s) Taken					
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental Impact	WO-Work Order				CR-Creek/Stream/River (please specify)	
E-Equipment Failure	G-Grease	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup				D]-Ditch	
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill	HC-Hydro Cleaned				DR-Drop Inlet	
R-Rainfall	RG-Roots & Grease		HR-Hand Rodded				GR-Ground Surface	
RO-Roots	V-Vandalism		EN-Referred to Engineering				PA-Paved Area	
			PN-Public Notification				CB-Contained in Building	

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
Harrison & Boswell	2-377C	3/4/2020	3/4/2020	2000	RG,D	NEAH	EC,HC	GR,DR
2200 Lee St.	6-37A	3/29/2020	3/29/2020	1100	D	NEAH	EC,HC	GR

Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."