## Sanitary Sewer Overflow Monthly Report

								Broad & St. Louis St.		Location		RO-Roots V-V			HC-Hydro Clean	E-Equipment Failure G		CO-Construction D	Cause(s) of SSO			acility Name: Bate
R. J. St.								2-167		Manhole #		V-Vandalism	RG-Roots & Grease	Failure/Break	LF-Line	G-Grease		D-Debris				Batesville Water Utilities
								7/24/2023	880	State Date of					EFK-Evidence of Fish Kill	OEHC-Observed or Evidence of Human Contact		NEAH-No			Sa	
					30			7/24/2023	SSO	End Date of							Impact	NEAH-No Evidence of Adverse of Environmental	SSO Impact	Sumi		Permit Number:
								200	gallons)	Estimated						of Human Contact		e of Environmental	#	Summery Report Code Descriptions	verflows This	r: AR0020702
8/2/23								RG		Cause of SSO	P	EN-F				EC-E		WO-Work Order	Action(s) Taken		Monitoring Pe	
								NEAH	IIIIpact	Environmental	PN-Public Notification	EN-Referred to Engineering	HR-Hand Rodded		HC-Hydro Cleaned	EC-Environmental Cleanup					riod	Reporting Period(Month/Year):
								HC,EC	to Address SSO	Action(s) Taken	CB-C					0		CR-Creek/S	Ultimat			onth/Year):
								Paved	Location	Ultimate Discharge	CB-Contained in Building	PA-Paved Area	GR-Ground Surface		DR-Drop Inlet	DI-Ditch	Tourne (Produce opening)	CR-Creek/Stream/River (please specify)	Ultimate Discharge Location			July 2023

significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations." responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly "I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that