

# Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities    Permit Number: AR0020702    Reporting Period(Month/Year): June 2015

No Sanitary Sewer Overflows This Monitoring Period

Cause(s) of SSO		Summary Report Code Descriptions			Action(s) Taken	Ultimate Discharge Location
		SSO Impact				
CO-Construction	D-Debris	NEAH-No Evidence of Adverse of Environmental Impact			WO-Work Order	CR-Creek/Stream/River (please specify)
	E-Equipment Failure	OEHC-Observed or Evidence of Human Contact			EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	EFK-Evidence of Fish Kill			HC-Hydro Cleaned	DR-Drop Inlet
	R-Rainfall				HR-Hand Rodded	GR-Ground Surface
RO-Roots	RG-Roots & Grease				EN-Referred to Engineering	PA-Paved Area
	V-Vandalism				PN-Public Notification	CB-Contained in Building

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
875 Lawerance	2-273	6/17/2015	6/17/2015	200	R,G	NEAH	EC,HC	GR

Date

7-7-15

Signature of Cognizant or Ranking Official  
 "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."