

Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): October 2016

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions					
Cause(s) of SSO			SSO Impact		Ultimate Discharge Location
CO-Construction	D-Debris		NEAH-No Evidence of Adverse of Environmental Impact		WO-Work Order
E-Equipment Failure	G-Grease		OEHC-Observed or Evidence of Human Contact		EC-Environmental Cleanup
HC-Hydro Clean	LF-Line Failure/Break		EFFK-Evidence of Fish Kill		HC-Hydro Cleaned
R-Rainfall	RG-Roots & Grease			HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism			EN-Referred to Engineering	PA-Paved Area
				PN-Public Notification	CB-Contained in Building

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
Super 8 Motel N. St. Louis	3-48	10/16/2016	10/16/2016	Undetermined	G	NEAH NEAH	HC, EC HC, EC	GR, DI GR
1615 N. Central	1-236A	10/27/2016	10/27/2016	200	RG			

Signature of Cognizant Ranking Official


Date
 11-8-16

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."