

Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): October 2017

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions		
Cause(s) of SSO	SSO Impact	Action(s) Taken
CO-Construction	NEAH-No Evidence of Adverse of Environmental Impact	WO-Work Order
E-Equipment Failure	OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup
HC-Hydro Clean	EFK-Evidence of Fish Kill	HC-Hydro Cleaned
R-Rainfall		HR-Hand Rodded
RO-Roots		EN-Referred to Engineering
		PN-Public Notification
		DI-Ditch
		DR-Drop Inlet
		GR-Ground Surface
		PA-Paved Area
		CB-Contained in Building
		CR-Creek/Stream/River (please specify)

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
1740 Arch st.	1-267A	10/05/2017	10/05/2017	30	D	NEAH	EC,HC	GR
13 Wildwood	050099	10/18/2017	10/18/2017	20	G	NEAH	EC,HC	GR

[Signature]
 Signature of Cognizant or Ranking Official

11-20-17
 Date

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."