

Sanitary Sewer Overflow Monthly Report

Facility Name: Batesville Water Utilities Permit Number: AR0020702 Reporting Period(Month/Year): December 2022

No Sanitary Sewer Overflows This Monitoring Period

Summary Report Code Descriptions			
Cause(s) of SSO	SSO Impact	Action(s) Taken	Ultimate Discharge Location
CO-Construction	D-Debris	WO-Work Order	CR-Creek/Stream/River (please specify)
E-Equipment Failure	G-Grease OEHC-Observed or Evidence of Human Contact	EC-Environmental Cleanup	DI-Ditch
HC-Hydro Clean	LF-Line Failure/Break	HC-Hydro Cleaned	DR-Drop Inlet
R-Rainfall	RG-Roots & Grease	HR-Hand Rodded	GR-Ground Surface
RO-Roots	V-Vandalism	EN-Referred to Engineering PN-Public Notification	PA-Paved Area CB-Contained in Building

Location	Manhole #	State Date of SSO	End Date of SSO	Estimated Volume (in gallons)	Cause of SSO	Environmental Impact	Action(s) Taken to Address SSO	Ultimate Discharge Location
3120 Peggy	070003	12/13/2022	12/13/2022	1000	RO, R	NEAH	EC, HC	DI
1401 N. Central	1-235	12/17/2022	12/17/2022	200	RG	NEAH	EC, HC	PA

Signature of Cognizant or Ranking Official: Rush Sum

Date: 1/3/23

"I certify under penalty of law that this document and all attachments were prepared under my direction of supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."